AUTOCAR INDIA

# SPARE PARTS PRICE SURVEY




NEW INDIA FLOATER MEDICLAIM

- Single floater sum insured for entire family.
- Hospitalisation benefit for floater Sum Insured of ₹ 2 lakhs, ₹ 3 lakhs, ₹ 5 lakhs & ₹ 8 lakhs.

For more details on risk factors, terms & conditions please read sales brochure carefully before concluding a sale. *Condition apply

NEW INDIA ASSURANCE
दि न्यू इन्डिया एश्योरन्स कंपनी लिमिटेड
The New India Assurance Co. Ltd

www.newindia.co.in
Toll free 1800-209-1415

Regd & Head Office:
New India Assurance Bldg., 87, M.G. Road, Fort, Mumbai-400 001, INDIA

IRDAI REGN. No. 190 CIN : U 99999 MH 1919 GOI 000 526 UIN No. NIAHLIP13030V011213 URN No. : NIA/16-17/PC/292

# SPARE A THOUGHT

Our comprehensive price survey of spare parts for over 150 of India's most popular cars is back. **Sergius Barretto** and **Siddhant Ghalla** crunch the numbers.

For most people, buying a car is a major financial decision and at times a complex one. While we commonly tend to link the affordability of a car to its ex-showroom or on-road price, purchasing and owning a car comes with a long list of other costs. While some costs are obvious, such as insurance and fuel, others, such as repairs and maintenance, are more implicit and abstract. Of course, people do talk about how the service costs for a particular brand, but such assertions are not always based on hard numbers. Thus, the Autocar *Spare Parts Survey*.

At the time of purchase, two cars might cost roughly the same, but the burden on your pocket may differ substantially over the years. The cost of ownership of a vehicle is made up of a number of components, including but not limited to the cost of spares, servicing costs, service intervals, component service life, and even depreciation. The multiplicity of these components is what makes calculating the accurate cost of ownership of a vehicle a tricky affair. →

**The Alto narrowly beats the Nano to have the lowest basket price amongst budget hatchbacks.**

## BUDGET HATCHBACKS

| | DATSUN REDIGO | HYUNDAI EON 0.8 | HYUNDAI EON 1.0 | MARUTI ALTO 800 | MARUTI ALTO K10 | RENAULT KWID 800 | RENAULT KWID 1.0 | TATA NANO |
|---|---|---|---|---|---|---|---|---|
| **SERVICE PARTS** | | | | | | | | |
| Air Filter | 166 | 164 | 238 | 225 | 185 | 166 | 166 | 166 |
| Oil Filter | 112 | 96 | 96 | 90 | 90 | 112 | 112 | 94 |
| Fuel Filter | 244 | 397 | 397 | 320 | 320 | 244 | 244 | 55 |
| Wiper Blades (pair) | 349 | 551 | 551 | 255 | 255 | 349 | 349 | 230 |
| Spark Plug (for entire set) | 122 | 228 | 228 | 375 | 300 | 122 | 122 | 130 |
| Timing Belt/ Chain | 1459 | 629 | 1331 | 590 | 631 | 1459 | 2620 | 481 |
| Fan Belt/ Drivebelt | 192 | 152 | 915 | 150 | 240 | 184 | 184 | 126 |
| Front Brake Pads (set of 4) | 1149 | 1062 | 1062 | 1050 | 2280 | 1149 | 1149 | 776 |
| **MECHANICAL PARTS** | | | | | | | | |
| A/c Evaporator Coil | 569 | 1699 | 1699 | 1450 | 1800 | 1800 | 1800 | 3009 |
| Radiator Hose Set | 185 | 453 | 453 | 160 | 235 | 480 | 480 | 310 |
| Front Strut/ Shock Absorber | 1361 | 1156 | 1156 | 1185 | 1480 | 1449 | 1449 | 1665 |
| Front Brake Disc/ Drum | 952 | 941 | 1486 | 630 | 675 | 952 | 952 | 1121 |
| Front Suspension Lower Arm | 1300 | 706 | 706 | 635 | 635 | 1300 | 1300 | 944 |
| Clutch and Pressure Plate | 2500 | 1738 | 2673 | 1725 | 1800 | 2500 | 2500 | 1180 |
| Clutch Release Bearing | 2068* | 579 | 579 | 580 | 580 | 2068 | 2068 | 381 |
| **ACCIDENT REPAIR PARTS** | | | | | | | | |
| Front bumper | 1429 | 1168 | 1168 | 1195 | 1250 | 1429 | 1429 | 1625 |
| Wheel rim (each) | 1126 | 687 | 687 | 574 | 965 | 1290 | 1290 | 937 |
| Front fender | 2216 | 998 | 998 | 950 | 1119 | 1729 | 1729 | 2773 |
| Bonnet | 4076 | 2769 | 2769 | 2584 | 2975 | 4076 | 4076 | 4130 |
| Radiator | 1950 | 2343 | 2499 | 2100 | 2475 | 1950 | 2076 | 1890 |
| Front door | 7326 | 4345 | 4345 | 5200 | 5200 | 6280 | 6280 | 4187 |
| Bootlid/ tailgate | 5318 | 3503 | 3503 | 4894 | 4700 | 5318 | 5318 | 4338 |
| Headlight Assy. (each with bulb) | 1819 | 2381 | 2381 | 2013 | 2129 | 2200 | 2200 | 1812 |
| Tail-light Assy. (each with bulb) | 1328 | 1328 | 1328 | 883 | 1346 | 1529 | 1529 | 786 |
| Front windscreen glass | 2900 | 2673 | 2673 | 2900 | 2900 | 2900 | 2900 | 2529 |
| Side mirror (with casing) | 578 | 578 | 578 | 443 | 500 | 1150 | 1208 | 704 |
| Total Price Basket | 40726 | 33324 | 36499 | 33156 | 37065 | 44185 | 45530 | 36379 |
| Vehicle price (ex showroom, Mumbai, base version) | 254062 | 344061 | 465233 | 330286 | 369084 | 298513 | 419847 | 238201 |
| Percentage of parts to car price | 16.0% | 9.7% | 7.8% | 10.0% | 10.0% | 14.8% | 10.8% | 15.3% |

*Estimated based on Kwid price




NOTE: Figures in blue are lowest, red are highest. Prices in rupees are M.R.P. (Mumbai), effective Aug-Nov 2016. Prices are indicative and may vary. All prices from manufacturers. N/A- Not Available/Not Applicable.

Sharing platforms, the Redigo and the Kwid have virtually identical part prices.

## ENTRY-LEVEL HATCHBACKS

| | CHEVY BEAT PETROL | CHEVY BEAT DIESEL | DATSUN GO | HYUNDAI i10 | MARUTI WAGONR | MARUTI CELERIO PETROL | MARUTI CELERIO DIESEL | NISSAN MICRA ACTIVE | TATA INDICA PETROL | TATA INDICA DIESEL | TATA TIAGO PETROL | TATA TIAGO DIESEL |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **SERVICE PARTS** | | | | | | | | | | | | |
| Air Filter | 252 | 477 | 232 | 247 | 190 | 185 | 259 | 232 | 313 | 313 | 455 | 321 |
| Oil Filter | 162 | 453 | 175 | 96 | 90 | 90 | 170 | 175 | 132 | 204 | 119 | 204 |
| Fuel Filter | 292 | 1376 | NA | 392 | 320 | 700 | 1254 | NA | 629 | 179 | 387 | 2242 |
| Wiper Blades (pair) | 599 | 599 | 295 | 469 | 265 | 280 | 280 | 994 | 359 | 359 | 511 | 511 |
| Spark Plug (for entire set) | 404 | NA | 125 | 316 | 300 | 300 | NA | 125 | 97 | NA | 258 | NA |
| Timing Belt/ Chain | 3540 | 1501 | 1190 | 629 | 631 | 631 | 840 | 1190 | 981 | 850 | 1607 | 931 |
| Fan Belt/ Drivebelt | 197 | 197 | 1214 | 152 | 240 | 240 | 225 | 692 | 313 | 516 | 457 | 457 |
| Front Brake Pads (set of 4) | 2354 | 2354 | 2306 | 1137 | 1048 | 2280 | 2280 | 2306 | 1587 | 1587 | 1468 | 1468 |
| **MECHANICAL PARTS** | | | | | | | | | | | | |
| A/c Evaporator Coil | 2900 | 2618 | 3971 | 1773 | 2165 | 1350 | 1350 | 2600 | 1987 | 1987 | 4731 | 4731 |
| Radiator Hose Set | 477 | 522 | 450 | 420 | 185 | 177 | 290 | 595 | 231 | 391 | 358 | 358 |
| Front Strut/ Shock Absorber | 1661 | 1730 | 1691 | 1092 | 1315 | 1450 | 1750 | 1774 | 1809 | 1809 | 1938 | 1938 |
| Front Brake Disc/ Drum | 1065 | 1065 | 930 | 999 | 675 | 960 | 960 | 1310 | 809 | 841 | 1053 | 1053 |
| Front Suspension Lower Arm | 2400 | 2400 | 1289 | 1130 | 916 | 1050 | 1325 | 1968 | 1949 | 1949 | 3132 | 3132 |
| Clutch and Pressure Plate | 2413 | 3255 | 2974 | 1711 | 1800 | 1900 | 3050 | 2722 | 2634 | 2474 | 3139 | 1442 |
| Clutch Release Bearing | 1003 | 3518 | NA | 579 | 580 | 580 | 3137 | 4970 | 610 | 610 | 715 | 715 |
| **ACCIDENT REPAIR PARTS** | | | | | | | | | | | | |
| Front bumper | 1599 | 1599 | 1490 | 1337 | 1223 | 1300 | 1300 | 2030 | 2398 | 2398 | 1774 | 1774 |
| Wheel rim (each) | 954 | 954 | 950 | 732 | 785 | 860 | 1075 | 1143 | 795 | 795 | 844 | 844 |
| Front fender | 1891 | 1891 | 1295 | 1068 | 1374 | 1375 | 1375 | 1790 | 2977 | 2977 | 2192 | 2192 |
| Bonnet | 4034 | 4034 | 4200 | 3247 | 2878 | 2990 | 2990 | 5250 | 4700 | 4700 | 7046 | 7046 |
| Radiator | 3015 | 5779 | 2490 | 2526 | 2527 | 2450 | 3100 | 2980 | 4479 | 4885 | 3200 | 3133 |
| Front door | 7000 | 7000 | 6980 | 4999 | 5219 | 5250 | 5250 | 9980 | 8843 | 8843 | 7652 | 7652 |
| Bootlid/ tailgate | 5277 | 5277 | 5690 | 3711 | 5529 | 4800 | 4800 | 6190 | 6156 | 6156 | 6131 | 6131 |
| Headlight Assy. (each with bulb) | 4122 | 4122 | 2720 | 2995 | 2293 | 2444 | 2444 | 2723 | 1718 | 1718 | 2836 | 2836 |
| Tail-light Assy. (each with bulb) | 1426 | 1426 | 1110 | 1397 | 1148 | 1346 | 1346 | 1320 | 1443 | 1443 | 1370 | 1370 |
| Front windscreen glass | 3466 | 3466 | 3895 | 2980 | 2922 | 3200 | 3200 | 3550 | 4135 | 4135 | 4569 | 4569 |
| Side mirror (with casing) | 1364 | 1364 | 768 | 762 | 554 | 900 | 900 | 1032 | 1252 | 1252 | 1149 | 1149 |
| Total Price Basket | 53867 | 58977 | 48430 | 36896 | 37172 | 39088 | 44950 | 59641 | 53336 | 53371 | 59091 | 58199 |
| Vehicle price (ex showroom Mumbai, base version) | 457771 | 557842 | 353629 | 454248 | 398581 | 427915 | 533162 | 479827 | 421741 | 511925 | 342654 | 422340 |
| Percentage of parts to car price | 11.8% | 10.6% | 13.7% | 8.1% | 9.3% | 9.1% | 8.4% | 12.4% | 12.6% | 10.4% | 17.2% | 13.8% |




NEW INDIA TOP UP MEDI-CLAIM
Future Without Fear...
Total Cover Upto 30 Lacs | Tax Benefit* 80D | Hospital Cash
Get Well Benefit | 74+Day Care Procedure | Covers Entire Family
For more details on risk factors, terms & conditions please read sales brochure carefully before concluding a sale. *Condition apply
NEW INDIA ASSURANCE
दि न्यू इन्डिया एश्योरन्स कंपनी लिमिटेड
The New India Assurance Co. Ltd
www.newindia.co.in
Toll free 1800-209-1415
Regd & Head Office: New India Assurance Bldg., 87, M.G. Road, Fort, Mumbai-400 001, INDIA
IRDAI REGN. No. 190 CIN : U 99999 MH 1919 GOI 000 526 UIN. NIAHLIP15004V011415. URN No. : NIA/16-17/PC/292

NEW INDIA GRIHA SUVIDHA POLICY
Starting as low as ₹3/- per day only
NO LIST - NO BILL of items are required
For more details on risk factors, terms & conditions please read sales brochure carefully before concluding a sale. *Condition apply
NEW INDIA ASSURANCE
दि न्यू इन्डिया एश्योरन्स कंपनी लिमिटेड
The New India Assurance Co. Ltd
www.newindia.co.in
Toll free 1800-209-1415
Regd & Head Office: New India Assurance Bldg., 87, M.G. Road, Fort, Mumbai-400 001, INDIA
IRDAI REGN. No. 190 CIN : U 99999 MH 1919 GOI 000 526 UIN No : IRDAN190P0001V01201516 URN No. : NIA/16-17/PC/292

Depsite being two segments above, the Swift spares are only slightly more expensive than the Alto's.

← There is, however, a simpler way around this. The cost of spare parts of a car is a great indicator of its cost of ownership. It is critical that these costs are not considered synonymous to the cost of ownership. It is merely a good indicator, and should always be considered in conjunction with other information such as the service life of components and the manufacturer-recommended service intervals. Another factor that needs to be kept in mind is the service package. Several manufacturers and dealers today offer service packages that, for a fixed prepaid sum, cover all your servicing needs over a certain period. These packages also help you hedge against future ownership expenses as well as inflation.

Autocar India's *Spare Parts Survey*, an extensive collection and analysis of the cost of spares of more than 150 cars currently on sale in India, allows you to compare the indicative cost of ownership of one vehicle to that of any other. In this survey, the spare parts have been grouped into three categories: service parts, mechanical parts and accident repair parts. Service parts are those that require routine, periodic changes, such as air and oil filters, wiper blades and brake pads. Mechanical parts require changing upon wearing out and failure, and include brake discs/ drums and shock absorbers. Accident repair parts include wheel rims or bumpers, and usually require changing only when damaged due to an accident.

The cost of all the surveyed spare parts for each car is listed at the bottom of the table as the total basket price, a quick-glance number to estimate how heavy a car might end up being on your wallet.

## BUDGET HATCHBACKS

Price sensitivity is particularly high for budget car buyers, making the cost of ownership an important metric for them. The budget car segment has seen some exciting disruption in the past year, what with the introduction of the Renault Kwid and the Datsun Redigo, both featuring more than 95 percent localisation.

Despite heavy localisation attempts by Renault and Datsun, it is the Maruti Alto 800, India's bestselling car, which features the lowest basket price in this segment. However, it is important to note that the Kwid, Redigo and Alto 800 are all priced similarly in terms of service parts; the disparity occurs in mechanical and accident repair parts. The Hyundai Eon 0.8 is close on the heels of the Alto 800, and the Eon 1.0 actually has a lower basket price than the Alto K10, demonstrating Hyundai's persistent effort to catch up with Maruti in terms of low-cost car ownership.

The Kwid and the Redigo feature identical prices for most service and mechanical parts since they are based on the same platform. The difference in their basket prices is mainly on account of the difference in accident repair parts. →

The low-selling Japanese duo of the Honda Brio and the Nissan Micra have mid-priced spares.

## MID-RANGE HATCHBACKS

| | CHEVROLET SAIL U-VA PETROL | FIAT PUNTO PURE PETROL | FIAT PUNTO PURE DIESEL | HONDA BRIO | HYUNDAI GRAND i10 PETROL | HYUNDAI GRAND i10 DIESEL | MARUTI SWIFT PETROL | MARUTI SWIFT DIESEL | NISSAN MICRA PETROL | NISSAN MICRA DIESEL | RENAULT PULSE PETROL | RENAULT PULSE DIESEL | TATA BOLT PETROL | TATA BOLT DIESEL | TOYOTA ETIOS LIVA PETROL | TOYOTA ETIOS LIVA DIESEL |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **SERVICE PARTS** | | | | | | | | | | | | | | | | |
| Air Filter | 271 | 422 | 453 | 482 | 199 | 199 | 305 | 259 | 232 | 398 | 232 | 855 | 235 | 260 | 249 | 249 |
| Oil Filter | 162 | 215 | 432 | 166 | 96 | 459 | 90 | 390 | 175 | 370 | 175 | 541 | 132 | 396 | 347 | 499 |
| Fuel Filter | 582 | 540 | 1775 | 507 | 397 | 1245 | 356 | 1254 | NA | 1640 | NA | 1900 | 387 | 1829 | 1200 | 1001 |
| Wiper Blades (pair) | 623 | 799 | 799 | 900 | 469 | 469 | 385 | 385 | 994 | 994 | 800 | 800 | 625 | 625 | 599 | 599 |
| Spark Plug (for entire set) | 824 | 500 | NA | 420 | 1128 | NA | 780 | NA | 125 | NA | 125 | NA | 664 | NA | 638 | NA |
| Timing Belt/ Chain | 1038 | 890 | 2615 | 600 | 999 | 798 | 530 | 1160 | 1190 | 2980 | 1190 | 1897 | 743 | 3516 | 860 | 3090 |
| Fan Belt/ Drivebelt | 508 | 657 | 936 | 300 | 549 | 377 | 240 | 240 | 692 | 1221 | 692 | 1221 | 271 | 1119 | 687 | 2793 |
| Front Brake Pads (set of 4) | 2354 | 3590 | 3590 | 2400 | 1582 | 1582 | 1583 | 1583 | 2306 | 2306 | 2306 | 2306 | 1580 | 1580 | 2839 | 2839 |
| **MECHANICAL PARTS** | | | | | | | | | | | | | | | | |
| A/c Evaporator Coil | 2549 | 4390 | 4390 | 1686 | 3098 | 3098 | 1950 | 2050 | 2600 | 2600 | 2600 | 2600 | 1987 | 1987 | 2843 | 2843 |
| Radiator Hose Set | 559 | 919 | 325 | 500 | 517 | 820 | 129 | 194 | 595 | 847 | 595 | 847 | 262 | 157 | 634 | 1036 |
| Front Strut/ Shock Absorber | 2178 | 2195 | 2195 | 2300 | 1356 | 1356 | 1250 | 1800 | 1774 | 1774 | 1774 | 1774 | 1600 | 1600 | 1834 | 1834 |
| Front Brake Disc/ Drum | 1065 | 1390 | 1390 | 723 | 993 | 993 | 1137 | 1137 | 1310 | 1395 | 1395 | 1395 | 1711 | 1711 | 1841 | 1841 |
| Front Suspension Lower Arm | 2640 | 2090 | 2090 | 1700 | 1722 | 1722 | 2200 | 2200 | 1968 | 1968 | 1968 | 1968 | 1381 | 1381 | 1919 | 1919 |
| Clutch and Pressure Plate | 3473 | 3490 | 4964 | 2639 | 2574 | 5284 | 1820 | 3088 | 2722 | 9990 | 2722 | 11664 | 3139 | 3050 | 2929 | 5588 |
| Clutch Release Bearing | 715 | 638 | 638 | 700 | 579 | 1317 | 580 | 3137 | 4970 | 1194 | 4164 | 4164 | 610 | 625 | 912 | 912 |
| **ACCIDENT REPAIR PARTS** | | | | | | | | | | | | | | | | |
| Front bumper | 2805 | 2162 | 2162 | 1900 | 1441 | 1441 | 1735 | 1735 | 2030 | 2030 | 2827 | 2827 | 2301 | 2301 | 2566 | 2566 |
| Wheel rim (each) | 1244 | 799 | 799 | 1316 | 899 | 899 | 905 | 905 | 1143 | 1143 | 1143 | 1143 | 1322 | 1322 | 5336 | 5336 |
| Front fender | 1981 | 1880 | 1880 | 1800 | 1068 | 1068 | 650 | 650 | 1790 | 1790 | 1890 | 1890 | 1604 | 1604 | 1662 | 1662 |
| Bonnet | 5244 | 4715 | 4715 | 3277 | 2769 | 2769 | 3563 | 3563 | 5250 | 5250 | 5513 | 5513 | 4450 | 4450 | 5380 | 5380 |
| Radiator | 3455 | 2990 | 2990 | 2950 | 2499 | 2779 | 2500 | 3600 | 2980 | 4126 | 2980 | 3430 | 4956 | 4956 | 3655 | 3828 |
| Front door | 9100 | 4925 | 4925 | 5400 | 5411 | 5411 | 3500 | 3500 | 8460 | 8460 | 7250 | 7250 | 6923 | 6923 | 7484 | 7484 |
| Bootlid/ tailgate | 5975 | 3665 | 3665 | 5639 | 3656 | 3656 | 3500 | 3500 | 6190 | 6190 | 6500 | 6500 | 5214 | 5214 | 6287 | 6287 |
| Headlight Assy. (each with bulb) | 3249 | 2293 | 2293 | 3021 | 2293 | 2293 | 2794 | 2794 | 3385 | 3385 | 3927 | 3927 | 3688 | 3688 | 3499 | 3499 |
| Tail-light Assy. (each with bulb) | 1930 | 725 | 725 | 1022 | 1118 | 1118 | 1250 | 1250 | 3080 | 3080 | 1412 | 1412 | 1375 | 1375 | 1651 | 1651 |
| Front windscreen glass | 4368 | 4190 | 4190 | 3000 | 2997 | 2997 | 3000 | 3000 | 3550 | 3550 | 3550 | 3550 | 2950 | 2950 | 4165 | 4165 |
| Side mirror (with casing) | 1377 | 854 | 854 | 1350 | 1058 | 1058 | 1125 | 1125 | 1231 | 1231 | 1231 | 3022 | 1328 | 1328 | 1287 | 1287 |
| Total Price Basket | 60269 | 51923 | 55790 | 46698 | 41467 | 45208 | 37857 | 44499 | 60742 | 69912 | 58961 | 74396 | 51438 | 55947 | 63300 | 70185 |
| Vehicle price (ex showroom Mumbai, base version) | 507675 | 480152 | 589491 | 501099 | 516399 | 611093 | 504929 | 631811 | 577152 | 682871 | 531723 | 654695 | 489716 | 610936 | 557920 | 701124 |
| Percentage of parts to car price | 11.9% | 10.8% | 9.5% | 9.3% | 8.0% | 7.4% | 7.5% | 7.0% | 10.5% | 10.2% | 11.1% | 11.4% | 10.5% | 9.2% | 11.3% | 10.0% |

> Maruti's low-price supremacy is carried forward in almost all of its segments.

NEW INDIA's
FOR THE FIRST TIME IN INDIA
LONG TERM TWO WHEELER PACKAGE POLICY
SAVE UPTO 50% ON YOUR 3 YEARS TWO-WHEELER INSURANCE
PAY ONCE AND GET PEACE OF MIND FOR 3 YEARS
For more details on risk factors, terms & conditions please read sales brochure carefully before concluding a sale.
*Condition apply
NEW INDIA ASSURANCE
दि न्यू इन्डिया एश्योरन्स कंपनी लिमिटेड
The New India Assurance Co. Ltd
www.newindia.co.in
Toll free 1800-209-1415
Regd & Head Office: New India Assurance Bldg., 87, M.G. Road, Fort, Mumbai-400 001, INDIA
IRDAI REGN. No. 190 CIN : U 99999 MH 1919 GOI 000 526 UIN: IRDAN190P0003V01201415 URN No. : NIA/16-17/PC/292

PRIVATE CAR PACKAGE POLICY
• Loss or damage to the vehicle insured
• Personal Accident cover for Owner-driver
• No- claim discounts ranging from 20% to 50%
For more details on risk factors, terms & conditions please read sales brochure carefully before concluding a sale. *Condition apply
NEW INDIA ASSURANCE
दि न्यू इन्डिया एश्योरन्स कंपनी लिमिटेड
The New India Assurance Co. Ltd
www.newindia.co.in
Toll free 1800-209-1415
Regd & Head Office: New India Assurance Bldg., 87, M.G. Road, Fort, Mumbai-400 001, INDIA
IRDAI REGN. No. 190 CIN : U 99999 MH 1919 GOI 000 526 UIN. IRDAN190P0042V01100001 URN No. : NIA/16-17/PC/292

The i20 and the Baleno are close competitors and are closely matched in terms of spare parts prices too.

> "Ford beating Maruti and Hyundai in spare parts prices is a commendable feat."

Ford's hard work on reducing service costs has paid off; Figo has the lowest priced basket in its segment.

← The Tata Nano, while still the cheapest car in this segment to buy, is not the cheapest in terms of cost of spare parts. At Rs 36,279 for the basket, it potters in at third place, and also has a high parts percentage to car price value. This is mainly on account of the unusually high cost of its AC evaporating coil (Rs 3,009).

## ENTRY-LEVEL HATCHBACKS

The entry-level hatchback segment is where diesel engines make their most affordable appearance. The difference between petrol and diesel variants of the same car is approximately Rs 5,000. The difference is mainly on account of more expensive air, oil and fuel filters as well as clutch and pressure plates and clutch-release bearings. However, the variation between the spare part prices for petrol and diesel variants is negligible for Tata cars, which probably reflects on the economies of scale achieved by the carmaker with respect to diesel drivetrains.

In this segment, it is Hyundai that leads in terms of affordability of spares, with its basket price totalling Rs 36,896 for the i10. Close behind is the Maruti WagonR, followed by the Maruti Celerio petrol and diesel. However, it is noteworthy that most Maruti service parts are still, on an average, cheaper than the Hyundai's.

## PREMIUM HATCHBACKS

| | FIAT PUNTO EVO PETROL | FIAT PUNTO EVO DIESEL | FORD FIGO PETROL | FORD FIGO DIESEL | HONDA JAZZ PETROL | HONDA JAZZ DIESEL | HYUNDAI i20 PETROL | HYUNDAI i20 DIESEL | MAHINDRA VERITO VIBE | MARUTI BALENO PETROL | MARUTI BALENO DIESEL | VW POLO PETROL | VW POLO DIESEL | VW POLO TSI |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **SERVICE PARTS** | | | | | | | | | | | | | | |
| Air Filter | 422 | 453 | 226 | 226 | 482 | 295 | 321 | 321 | 635 | 310 | 450 | 307 | 392 | 788 |
| Oil Filter | 215 | 432 | 90 | 399 | 166 | 425 | 96 | 459 | 550 | 90 | 390 | 325 | 420 | 670 |
| Fuel Filter | 540 | 1775 | 356 | 1406 | 507 | 1320 | 496 | 2050 | 1524 | 200 | 1700 | 1202 | 2626 | 1834 |
| Wiper Blades (pair) | 799 | 799 | 375 | 375 | 950 | 950 | 766 | 766 | 644 | 270 | 270 | 594 | 594 | 594 |
| Spark Plug (for entire set) | 500 | NA | 400 | NA | 420 | NA | 1128 | NA | NA | 780 | NA | 900 | NA | 3512 |
| Timing Belt/ Chain | 890 | 2615 | 631 | 1238 | 600 | 1150 | 999 | 798 | 2396 | 2290 | 1160 | 4094 | 2980 | 5712 |
| Fan Belt/ Drivebelt | 657 | 936 | 150 | 462 | 450 | 1000 | 841 | 377 | 1099 | 320 | 420 | 1327 | 976 | 1939 |
| Front Brake Pads (set of 4) | 3590 | 3590 | 1583 | 1583 | 2850 | 2850 | 1579 | 1579 | 2395 | 2145 | 2145 | 1844 | 1844 | 1844 |
| **MECHANICAL PARTS** | | | | | | | | | | | | | | |
| A/c Evaporator Coil | 4390 | 4390 | 1900 | 1900 | 2400 | 2400 | 3498 | 3498 | 5400 | 2600 | 2600 | 4707 | 4707 | 4707 |
| Radiator Hose Set | 919 | 325 | 124 | 122 | 400 | 500 | 468 | 548 | 582 | 265 | 520 | 507 | 1889 | 2371 |
| Front Strut/ Shock Absorber | 2195 | 2195 | 788 | 788 | 2200 | 3200 | 1497 | 1497 | 2452 | 1650 | 1890 | 1819 | 1861 | 1861 |
| Front Brake Disc/ Drum | 1390 | 1390 | 1137 | 1137 | 1560 | 1560 | 1235 | 1235 | 2890 | 1075 | 1075 | 2174 | 2174 | 2174 |
| Front Suspension Lower Arm | 2090 | 2090 | 2200 | 2200 | 1750 | 1750 | 1293 | 1293 | 2073 | 1200 | 1200 | 1300 | 1300 | 1300 |
| Clutch and Pressure Plate | 3490 | 4964 | 1616 | 3605 | 2639 | 8950 | 4364 | 6621 | 5770 | 3125 | 3088 | 11368 | 7320 | NA |
| Clutch Release Bearing | 638 | 638 | 1702 | 1702 | 700 | 1300 | 579 | 1317 | 1858 | 580 | 2625 | 1710 | 2250 | NA |
| **ACCIDENT REPAIR PARTS** | | | | | | | | | | | | | | |
| Front bumper | 2190 | 2190 | 1735 | 1735 | 2300 | 2300 | 1441 | 1441 | 4236 | 1750 | 1750 | 4060 | 4060 | 4060 |
| Wheel rim (each) | 799 | 799 | 950 | 950 | 825 | 825 | 856 | 856 | 1466 | 910 | 910 | 1151 | 1151 | 1151 |
| Front fender | 1990 | 1990 | 1196 | 1196 | 1175 | 1175 | 1258 | 1258 | 3999 | 1150 | 1150 | 3634 | 3679 | 3634 |
| Bonnet | 5390 | 5390 | 3563 | 3563 | 3495 | 3495 | 3499 | 3499 | 5999 | 3100 | 3100 | 5700 | 5700 | 5700 |
| Radiator | 2990 | 2990 | 3150 | 4310 | 3650 | 3750 | 3049 | 3692 | 5558 | 2150 | 3500 | 3900 | 3900 | 3900 |
| Front door | 4925 | 4925 | 5200 | 5200 | 5600 | 5600 | 5642 | 5642 | 9997 | 5530 | 5530 | 8041 | 8041 | 8041 |
| Bootlid/ tailgate | 3665 | 3665 | 5320 | 5320 | 4400 | 4400 | 3762 | 3762 | 6500 | 2850 | 2850 | 7574 | 7574 | 7574 |
| Headlight Assy. (each with bulb) | 2590 | 2590 | 2800 | 2800 | 3700 | 3700 | 3728 | 3728 | 3599 | 3649 | 3649 | 9000 | 9000 | 9000 |
| Tail-light Assy. (each with bulb) | 2490 | 2490 | 1294 | 1294 | 2700 | 2700 | 1998 | 1998 | 2132 | 2552 | 2552 | 1600 | 1600 | 1600 |
| Front windscreen glass | 4490 | 4490 | 3000 | 3000 | 2950 | 2950 | 2815 | 2815 | 4756 | 3565 | 3565 | 4382 | 4382 | 4254 |
| Side mirror (with casing) | 1290 | 1290 | 1333 | 1333 | 3577 | 3577 | 1344 | 1344 | 1183 | 1125 | 1125 | 850 | 850 | 850 |
| Total Price Basket | 55534 | 59401 | 42819 | 47844 | 52446 | 62122 | 48552 | 52394 | 79693 | 45231 | 49214 | 84070 | 81270 | 79070 |
| Vehicle price (ex showroom Mumbai, base version) | 608318 | 706993 | 481875 | 597514 | 602505 | 740746 | 589148 | 719588 | 678098 | 554970 | 672792 | 559202 | 709082 | 935046 |
| Percentage of parts to car price | 9.1% | 8.4% | 8.9% | 8.0% | 8.7% | 8.4% | 8.2% | 7.3% | 11.8% | 8.2% | 7.3% | 15.0% | 11.5% | 8.5% |

The four Tata cars in this segment, the Indica petrol and diesel, and the Tiago petrol and diesel, are on the expensive side of the spectrum, as are the Chevrolet Beat petrol and diesel and the Nissan Micra Active. At 17.2 percent, the Tiago petrol has a very high percentage of parts to car price. The Tatas' spare part prices are inflated again by the expensive AC evaporator coil (for the Tiago), as well as the generally expensive accident repair parts. The high cost of accident repair parts is an issue with the Beats and the Micra Active too.

## MID-RANGE HATCHBACKS

Hyundai and Maruti emerge as the most affordable manufacturers in this segment as well. The Maruti Swift petrol features one of the lowest basket prices across this survey, no doubt on account of massive economies of scale, coming close to its much-smaller sibling, the Alto K10. In fact, it is →

STUDENTS SAFETY INSURANCE POLICY
• Add on OPD cover
• Add on Hospitalisation cover
• Add on cover for parents/teaching/non teaching staff
• Basic Personal Accident upto ₹ 5 lacs sum insured per student
For more details on risk factors, terms & conditions please read sales brochure carefully before concluding a sale.
*Condition apply
NEW INDIA ASSURANCE
दि न्यू इन्डिया एश्योरन्स कंपनी लिमिटेड
The New India Assurance Co. Ltd
www.newindia.co.in
Toll free 1800-209-1415
Regd & Head Office: New India Assurance Bldg., 87, M.G. Road, Fort, Mumbai-400 001, INDIA
IRDAI REGN. No. 190 CIN : U 99999 MH 1919 GOI 000 526 UIN. IRDAN190P0004V01201314 URN No. : NIA/16-17/PC/292

PERSONAL ACCIDENT (GROUP) COMMERCIAL
• Restricted Cover - Death only
• Death, Permanent Disablement and Temporary Total Disablement.
For more details on risk factors, terms & conditions please read sales brochure carefully before concluding a sale.
*Condition apply
NEW INDIA ASSURANCE
दि न्यू इन्डिया एश्योरन्स कंपनी लिमिटेड
The New India Assurance Co. Ltd
www.newindia.co.in
Toll free 1800-209-1415
Regd & Head Office: New India Assurance Bldg., 87, M.G. Road, Fort, Mumbai-400 001, INDIA
IRDAI REGN. No. 190 CIN : U 99999 MH 1919 GOI 000 526 UIN. IRDAN190P0003V01201314 URN No. : NIA/16-17/PC/292

The Verito has the distinction of the most expensive price basket.

← more affordable in every category of spare parts as compared to its peers. The diesel variant scores equally well.

The Hyundai Grand i10 follows the Swift. The outlier, though, is the Renault Pulse diesel – its basket price is a whopping

> “Despite being more premium, the Zest has a lower-priced basket than the Indigo eCS.”

Rs 74, 396. That’s nearly 70 percent more than that of the Swift diesel and 35 percent more than the average in this segment. This high basket price is driven by expensive service parts and an unusually expensive clutch and pressure plate, and clutch release bearing; an anomaly also evident in its badge-engineered sibling, the Nissan Micra diesel.

The Toyota Etios Liva is yet another expensive mid-size hatchback in terms of spare prices, primarily due to its expensive accident repair parts. At Rs 42,971, the Liva petrol’s accident repair parts costs are nearly double than that of the Swift petrol’s.

## PREMIUM HATCHBACKS

Ford has worked hard to improve its service infrastructure and lower the ownership cost of its cars, evident in the fact that the Figo petrol and diesel variants feature the lowest basket price in this segment. In fact, the Figo’s cost of service parts is nearly half that of the Maruti Baleno or the Hyundai i20. On the whole though, the Maruti Baleno and the Hyundai i20 are not that far behind the Figo. Notably, the Baleno diesel parts account for just 6.7 percent of the car price.

Most expensive of the lot, unsurprisingly, is the VW Polo. VW is infamous for its high →

Cheaper bootlid makes the Figo Aspire’s price basket lower than that of the Figo hatchback.

## ENTRY-LEVEL SEDANS

| | CHEVROLET SAIL PETROL | CHEVROLET SAIL DIESEL | FIAT LINEA CLASSIC PETROL | FIAT LINEA CLASSIC DIESEL | FORD FIGO ASPIRE PETROL | FORD FIGO ASPIRE DIESEL | HONDA AMAZE PETROL | HONDA AMAZE DIESEL | HYUNDAI XCENT PETROL | HYUNDAI XCENT DIESEL | MAHINDRA VERITO | MARUTI SWIFT DZIRE PETROL | MARUTI SWIFT DZIRE DIESEL | TATA INDIGO ECS PETROL | TATA INDIGO ECS DIESEL | TATA ZEST PETROL | TATA ZEST DIESEL | TOYOTA ETIOS PETROL | TOYOTA ETIOS DIESEL |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **SERVICE PARTS** | | | | | | | | | | | | | | | | | | | |
| Air Filter | 271 | 271 | 422 | 453 | 226 | 226 | 482 | 295 | 199 | 199 | 635 | 305 | 259 | 313 | 313 | 235 | 260 | 249 | 249 |
| Oil Filter | 162 | 453 | 215 | 432 | 90 | 399 | 166 | 425 | 96 | 459 | 550 | 90 | 390 | 132 | 204 | 132 | 396 | 347 | 499 |
| Fuel Filter | 582 | 1376 | 540 | 1775 | 356 | 1406 | 507 | 1320 | 397 | 1245 | 1524 | 356 | 1254 | 629 | 179 | 387 | 1829 | 1200 | 1001 |
| Wiper Blades (pair) | 623 | 623 | 799 | 799 | 375 | 375 | 900 | 900 | 469 | 469 | 644 | 385 | 385 | 336 | 359 | 625 | 625 | 599 | 599 |
| Spark Plug (for entire set) | 824 | NA | 500 | NA | 400 | NA | 420 | NA | 1128 | NA | NA | 780 | NA | 388 | NA | 664 | NA | 638 | N/A |
| Timing Belt/ Chain | 1038 | 1501 | 890 | 2615 | 631 | 1238 | 600 | 1150 | 999 | 798 | 2396 | 530 | 1160 | 981 | 850 | 743 | 3516 | 860 | 3090 |
| Fan Belt/ Drivebelt | 508 | 719 | 657 | 936 | 150 | 462 | 300 | 400 | 549 | 377 | 1099 | 240 | 240 | 313 | 516 | 271 | 1119 | 687 | 2793 |
| Front Brake Pads (set of 4) | 2354 | 2354 | 3590 | 3590 | 1583 | 1583 | 2800 | 2800 | 1582 | 1582 | 2395 | 1583 | 1583 | 1587 | 1587 | 1580 | 1580 | 2839 | 2839 |
| **MECHANICAL PARTS** | | | | | | | | | | | | | | | | | | | |
| A/c Evaporator Coil | 2549 | 2549 | 4390 | 4390 | 1900 | 1900 | 1686 | 1686 | 3098 | 3098 | 5400 | 1950 | 2050 | 3686 | 3686 | 1987 | 1987 | 2843 | 2843 |
| Radiator Hose Set | 559 | 592 | 919 | 325 | 124 | 122 | 500 | 750 | 517 | 820 | 582 | 129 | 194 | 231 | 182 | 262 | 157 | 634 | 1036 |
| Front Strut/ Shock Absorber | 2178 | 2178 | 2195 | 2195 | 788 | 788 | 2300 | 2300 | 1687 | 1356 | 2452 | 1250 | 1800 | 2759 | 2555 | 1600 | 1600 | 1834 | 1834 |
| Front Brake Disc/ Drum | 1065 | 1222 | 1390 | 1390 | 1137 | 1137 | 1050 | 1050 | 993 | 993 | 2890 | 1137 | 1137 | 841 | 841 | 1711 | 1711 | 1841 | 1841 |
| Front Suspension Lower Arm | 2640 | 2640 | 2090 | 2090 | 2200 | 2200 | 1700 | 1700 | 1722 | 1722 | 2073 | 2200 | 2200 | 4125 | 4125 | 1381 | 1381 | 1919 | 1919 |
| Clutch and Pressure Plate | 3473 | 5378 | 3490 | 4964 | 1616 | 3605 | 2639 | 8950 | 2574 | 5284 | 5770 | 1820 | 3088 | 3519 | 3890 | 3139 | 3050 | 2929 | 5588 |
| Clutch Release Bearing | 715 | 6045 | 638 | 638 | 1702 | 1702 | 700 | 2900 | 579 | 1317 | 1858 | 580 | 3137 | 610 | 715 | 610 | 625 | 912 | 912 |
| **ACCIDENT REPAIR PARTS** | | | | | | | | | | | | | | | | | | | |
| Front bumper | 2805 | 2805 | 2099 | 2099 | 1735 | 1735 | 2100 | 2100 | 1441 | 1441 | 4236 | 1735 | 1735 | 3769 | 3769 | 2301 | 2301 | 2566 | 2566 |
| Wheel rim (each) | 1244 | 1244 | 1049 | 1049 | 950 | 950 | 700 | 700 | 899 | 899 | 1466 | 905 | 905 | 844 | 844 | 885 | 844 | 5336 | 5336 |
| Front fender | 1981 | 1981 | 1828 | 1828 | 1196 | 1196 | 1800 | 1800 | 1068 | 1068 | 3999 | 650 | 650 | 2977 | 3017 | 1604 | 1604 | 1662 | 1662 |
| Bonnet | 5244 | 5244 | 5990 | 5990 | 3563 | 3563 | 3091 | 3091 | 2769 | 2769 | 5999 | 3563 | 3563 | 4700 | 4700 | 4450 | 4450 | 5380 | 5380 |
| Radiator | 3455 | 4349 | 2990 | 2990 | 3150 | 4310 | 2950 | 4100 | 2499 | 2779 | 5558 | 3200 | 3600 | 4479 | 5172 | 4956 | 4956 | 3655 | 3828 |
| Front door | 9100 | 9100 | 4925 | 4925 | 5200 | 5200 | 4800 | 4800 | 5411 | 5411 | 9997 | 3500 | 3500 | 8843 | 8843 | 6923 | 6923 | 7484 | 7484 |
| Bootlid/ tailgate | 6911 | 6911 | 5397 | 5397 | 3000 | 3000 | 5796 | 5796 | 3299 | 3299 | 6500 | 3100 | 3100 | 7705 | 7705 | 5026 | 5026 | 4701 | 4701 |
| Headlight Assy. (each with bulb) | 3249 | 3249 | 4240 | 4240 | 2800 | 2800 | 3021 | 3021 | 2293 | 2293 | 3599 | 3094 | 3094 | 4783 | 4783 | 3584 | 3584 | 3499 | 3499 |
| Tail-light Assy. (each with bulb) | 1992 | 1992 | 2910 | 2910 | 1399 | 1399 | 1900 | 1900 | 1397 | 1397 | 2132 | 1142 | 1142 | 1187 | 1187 | 2262 | 2262 | 1745 | 1745 |
| Front windscreen glass | 4368 | 4368 | 4190 | 4190 | 3000 | 3000 | 3000 | 3000 | 2997 | 2997 | 4756 | 3000 | 3000 | 4388 | 4388 | 2950 | 2950 | 4165 | 4165 |
| Side mirror (with casing) | 1377 | 1377 | 854 | 854 | 1333 | 1333 | 1350 | 1350 | 1058 | 1058 | 1183 | 1125 | 1125 | 1252 | 1252 | 1503 | 1503 | 1287 | 1287 |
| Total Price Basket | 61267 | 70521 | 59197 | 63064 | 40604 | 45629 | 47258 | 58284 | 41720 | 45130 | 79693 | 38349 | 44291 | 65377 | 65662 | 51771 | 56239 | 61807 | 68692 |
| Vehicle price (ex showroom Mumbai, base version) | 610758 | 749537 | 663580 | 771371 | 560940 | 677268 | 589380 | 717771 | 569758 | 661431 | 769264 | 559629 | 696073 | 504569 | 562128 | 546842 | 667738 | 683655 | 802394 |
| Percentage of parts to car price | 10.0% | 9.4% | 8.9% | 8.2% | 7.2% | 6.7% | 8.0% | 8.1% | 7.3% | 6.8% | 10.4% | 6.9% | 6.4% | 13.0% | 11.7% | 9.5% | 8.4% | 9.0% | 8.6% |




PERSONAL ACCIDENT-INDIVIDUAL RETAIL

• Restricted Cover - Death only
• Death, Permanent Disablement and Temporary Total Disablement.
For more details on risk factors, terms & conditions please read sales brochure carefully before concluding a sale.
*Condition apply

NEW INDIA ASSURANCE
दि न्यू इन्डिया एश्योरन्स कंपनी लिमिटेड
The New India Assurance Co. Ltd
www.newindia.co.in
Toll free 1800-209-1415
Regd & Head Office:
New India Assurance Bldg., 87, M.G. Road, Fort, Mumbai-400 001, INDIA
IRDAI REGN. No. 190 CIN : U 99999 MH 1919 GOI 000 526 UIN. IRDAN190P0002V01201314 URN No. : NIA/16-17/PC/292

OFFICE PROTECTION SHIELD (GENERAL) (MULTIPLE BEYOND 2 CRORES)

• Multi Peril policy to meet each and every requirement of office establishments.
• Can be given to various professionals like doctors, engineers with modifications.
For more details on risk factors, terms & conditions please read sales brochure carefully before concluding a sale. *Condition apply

NEW INDIA ASSURANCE
दि न्यू इन्डिया एश्योरन्स कंपनी लिमिटेड
The New India Assurance Co. Ltd
www.newindia.co.in
Toll free 1800-209-1415
Regd & Head Office:
New India Assurance Bldg., 87, M.G. Road, Fort, Mumbai-400 001, INDIA
IRDAI REGN. No. 190 CIN : U 99999 MH 1919 GOI 000 526 UIN.IRDAN190P0119V01100001 URN No. : NIA/16-17/PC/292

Among the top three selling sedans, the Maruti Ciaz has the cheapest price baskets.

> In the mid-size segment, VW and Skoda spares are nearly 40 percent costlier than Maruti's and Hyundai's.

ownership costs, evident in the Rs 84,070 basket price, nearly double than that of the Ford Figo petrol. The Polo's high price is driven by an unusually expensive fuel filter (for the diesel), timing belt, clutch and pressure plate, front door, headlight assembly and tailgate.

The Mahindra Verito Vibe is also pricey, with its Rs 79,693 basket price.

The Fiat Avventura and Punto Evo are not particularly well priced either, but an analysis of their numbers shows that their high cost of spares can be attributed largely to the high cost of accident repair parts.

## ENTRY-LEVEL SEDANS

The numbers in the entry-level sedan segment reflect the ones in the premium hatchback segment, an unsurprising observation since most entry-level sedans are based on premium hatchbacks.

Thus, the Ford Figo Aspire once again ranks No.1 in terms of affordability of its spare parts. In fact, the Figo Aspire's basket price is even lower than that of the Figo hatchback, on account of a cheaper tailgate. The Figo Aspires are followed by the Maruti Swift Dzires and the Hyundai Xcents.

At the top of the basket price spectrum sits the Mahindra Verito, asking for a lofty Rs 79,693. This high basket price is a result of the priciest mechanical and accident repair parts of the lot. We do not have spare parts price data for the VW Ameo yet, though reference to the premium hatchback table suggests that it could present a basket as expensive, if not more, as the Verito's. The Honda Amazes and Tata Bolts sit somewhere in the middle of the spectrum.

A curious observation is the disparity in basket price between the Tata Indigo eCS and the Zest. The basket price for the Indigo eCS is nearly 20 percent more than that of the Zest, despite the Zest being a more premium vehicle, driven by the higher prices for its mechanical and accident repair parts.

It is noteworthy that the Toyota Etios diesel holds the title for the most expensive service parts in this segment. Its brake pads, timing belt and fan belt are all more expensive than that of other entry-level sedans.

## MID-SIZE SEDANS

Maruti and Hyundai come back on top in the mid-size sedan segment with the Ciaz and the Verna. The Ciaz boasts the lowest prices for service parts and mechanical parts in this segment, though the cheapest accident repair parts are available for the Verna. →

The oil filter for every single petrol Maruti costs Rs 90.

## MID-SIZE SEDANS

| | FIAT LINEA PETROL | FIAT LINEA DIESEL | HONDA CITY PETROL | HONDA CITY DIESEL | HYUNDAI VERNA 1.4 PETROL | HYUNDAI VERNA 1.6 PETROL | HYUNDAI VERNA 1.4 DIESEL | HYUNDAI VERNA 1.6 DIESEL |
|---|---|---|---|---|---|---|---|---|
| **SERVICE PARTS** | | | | | | | | |
| Air Filter | 422 | 453 | 482 | 295 | 321 | 321 | 346 | 346 |
| Oil Filter | 215 | 432 | 166 | 425 | 219 | 219 | 459 | 459 |
| Fuel Filter | 540 | 1775 | 507 | 1320 | 397 | 397 | 2050 | 2050 |
| Wiper Blades (pair) | 799 | 799 | 975 | 975 | 984 | 984 | 984 | 984 |
| Spark Plug (for entire set) | 500 | NA | 1600 | NA | 1128 | 1128 | NA | NA |
| Timing Belt/ Chain | 890 | 2615 | 800 | 1150 | 1826 | 1826 | 798 | 798 |
| Fan Belt/ Drivebelt | 690 | 936 | 450 | 1000 | 699 | 699 | 377 | 377 |
| Front Brake Pads (set of 4) | 3590 | 3590 | 2850 | 2850 | 1259 | 1259 | 1259 | 1259 |
| **MECHANICAL PARTS** | | | | | | | | |
| A/c Evaporator Coil | 4390 | 4390 | 2400 | 2400 | 2467 | 2467 | 2467 | 2467 |
| Radiator Hose Set | 919 | 325 | 650 | 875 | 820 | 820 | 892 | 892 |
| Front Strut/ Shock Absorber | 2195 | 2195 | 3200 | 2500 | 1768 | 1768 | 1768 | 1768 |
| Front Brake Disc/ Drum | 1390 | 1390 | 1560 | 1560 | 1235 | 1235 | 1235 | 1235 |
| Front Suspension Lower Arm | 2090 | 2090 | 1800 | 1800 | 2359 | 2359 | 2359 | 2359 |
| Clutch and Pressure Plate | 3490 | 4964 | 2639 | 8950 | 4754 | 4754 | 6621 | 6621 |
| Clutch Release Bearing | 638 | 638 | 700 | 1300 | 1317 | 1317 | 1317 | 1317 |
| **ACCIDENT REPAIR PARTS** | | | | | | | | |
| Front bumper | 2099 | 2190 | 2349 | 2349 | 2477 | 2477 | 2477 | 2477 |
| Wheel rim (each) | 1049 | 1049 | 950 | 950 | 1175 | 1175 | 1175 | 1175 |
| Front fender | 1828 | 1828 | 1800 | 1800 | 1593 | 1593 | 1593 | 1593 |
| Bonnet | 5990 | 5990 | 4124 | 4124 | 3051 | 3051 | 3051 | 3051 |
| Radiator | 2990 | 2990 | 5464 | 5464 | 3049 | 3049 | 3876 | 3876 |
| Front door | 4925 | 4925 | 6908 | 6908 | 6599 | 6599 | 6599 | 6599 |
| Bootlid/ tailgate | 5397 | 5990 | 5052 | 5052 | 3688 | 3688 | 3688 | 3688 |
| Headlight Assy. (each with bulb) | 4240 | 4240 | 4700 | 4700 | 3381 | 3381 | 3381 | 3381 |
| Tail-light Assy. (each with bulb) | 2910 | 2910 | 1550 | 1550 | 1709 | 1709 | 1709 | 1709 |
| Front windscreen glass | 4190 | 5502 | 4900 | 4900 | 3216 | 3216 | 3216 | 3216 |
| Side mirror (with casing) | 854 | 2195 | 3120 | 3120 | 3220 | 3220 | 3220 | 3220 |
| Total Price Basket | 59230 | 66401 | 61696 | 68317 | 54711 | 54711 | 56917 | 56917 |
| Vehicle price (ex showroom Mumbai, base version) | 812614 | 930144 | 871263 | 1000314 | 833108 | 957995 | 967397 | 1088917 |
| Percentage of parts to car price | 7.3% | 7.1% | 7.1% | 6.8% | 6.6% | 5.7% | 5.9% | 5.2% |

| | MARUTI CIAZ PETROL | MARUTI CIAZ DIESEL | NISSAN SUNNY PETROL | NISSAN SUNNY DIESEL | RENAULT SCALA PETROL | RENAULT SCALA DIESEL | SKODA RAPID PETROL | SKODA RAPID DIESEL | VW VENTO PETROL | VW VENTO DIESEL | VW VENTO TSI |
|---|---|---|---|---|---|---|---|---|---|---|---|
| **SERVICE PARTS** | | | | | | | | | | | |
| Air Filter | 305 | 259 | 288 | 398 | 288 | 855 | 350 | 392 | 350 | 392 | 788 |
| Oil Filter | 90 | 390 | 175 | 370 | 175 | 541 | 670 | 420 | 670 | 420 | 670 |
| Fuel Filter | 390 | 1254 | NA | 1640 | NA | 1900 | NA | 1287 | 1202 | 2626 | 1834 |
| Wiper Blades (pair) | 430 | 430 | 800 | 800 | 800 | 800 | 594 | 594 | 594 | 594 | 594 |
| Spark Plug (for entire set) | 780 | NA | 176 | NA | 176 | NA | 300 | NA | 1272 | NA | 3512 |
| Timing Belt/ Chain | 1250 | 1160 | 1190 | 2980 | 1190 | 1897 | 4094 | 2977 | 4094 | 2980 | 5712 |
| Fan Belt/ Drivebelt | 240 | 470 | 1214 | 1221 | 1214 | 1221 | 1765 | 976 | 1765 | 976 | 1939 |
| Front Brake Pads (set of 4) | 2125 | 2125 | 3920 | 3920 | 2306 | 2306 | 1844 | 1844 | 1844 | 1844 | 1844 |
| **MECHANICAL PARTS** | | | | | | | | | | | |
| A/c Evaporator Coil | 1800 | 2650 | 2600 | 2600 | 2600 | 2600 | 4707 | 4707 | 4707 | 4707 | 4707 |
| Radiator Hose Set | 295 | 340 | 473 | 847 | 473 | 847 | 3762 | 3762 | 1483 | 1889 | 2371 |
| Front Strut/ Shock Absorber | 1900 | 3200 | 1960 | 1960 | 1960 | 1960 | 1861 | 1861 | 1819 | 1861 | 1861 |
| Front Brake Disc/ Drum | 1137 | 1137 | 1395 | 1395 | 1395 | 1395 | 2174 | 2174 | 2174 | 2174 | 2174 |
| Front Suspension Lower Arm | 1560 | 1560 | 1968 | 1968 | 1968 | 1968 | 1300 | 1300 | 1300 | 1300 | 1300 |
| Clutch and Pressure Plate | 2365 | 3320 | 4260 | 9990 | 4260 | 11664 | 5717 | 7320 | 5717 | 7320 | NA |
| Clutch Release Bearing | 1250 | 1250 | 4970 | 1194 | 4164 | 4164 | 1710 | 2250 | 1710 | 2250 | NA |
| **ACCIDENT REPAIR PARTS** | | | | | | | | | | | |
| Front bumper | 2690 | 2690 | 2350 | 2350 | 2975 | 2975 | 2150 | 2150 | 4330 | 4900 | 4330 |
| Wheel rim (each) | 1060 | 1060 | 1143 | 1143 | 1143 | 1143 | 1500 | 1151 | 1151 | 1151 | 1151 |
| Front fender | 1450 | 1450 | 2390 | 2390 | 2390 | 2350 | 4000 | 4000 | 4450 | 4450 | 4450 |
| Bonnet | 3900 | 3900 | 6885 | 6885 | 6250 | 6250 | 7419 | 7419 | 9000 | 9000 | 9000 |
| Radiator | 4315 | 5000 | 4000 | 4126 | 2980 | 4126 | 3900 | 3900 | 3900 | 3900 | 3900 |
| Front door | 6300 | 6300 | 13716 | 13716 | 9900 | 9900 | 11556 | 11556 | 11556 | 11556 | 11556 |
| Bootlid/ tailgate | 4800 | 4800 | 7400 | 7400 | 7770 | 7770 | 9213 | 9213 | 11600 | 11600 | 11600 |
| Headlight Assy. (each with bulb) | 4555 | 4555 | 3980 | 3980 | 3980 | 3980 | 4231 | 4231 | 9000 | 9000 | 9000 |
| Tail-light Assy. (each with bulb) | 1607 | 1607 | 2250 | 2250 | 2906 | 2906 | 2415 | 2415 | 3490 | 3490 | 3490 |
| Front windscreen glass | 5000 | 5000 | 3790 | 3790 | 3790 | 3790 | 4254 | 4254 | 4254 | 4382 | 4382 |
| Side mirror (with casing) | 3050 | 3050 | 1231 | 1231 | 1231 | 1856 | 850 | 850 | 850 | 850 | 850 |
| Total Price Basket | 54644 | 58957 | 74524 | 80544 | 68284 | 81164 | 82336 | 83003 | 94282 | 95612 | 93015 |
| Vehicle price (ex showroom Mumbai, base version) | 809338 | 890259 | 847373 | 941247 | 833672 | 944855 | 953077 | 946911 | 840445 | 975264 | 1070328 |
| Percentage of parts to car price | 6.8% | 6.6% | 8.8% | 8.6% | 8.2% | 8.6% | 8.6% | 8.8% | 11.2% | 9.8% | 8.7% |

SHOPKEEPERS INSURANCE (MULTIPLE LOCATIONS)

• Specially designed for various needs of shopkeepers.
• Discount in premium available on multiple covers.

For more details on risk factors, terms & conditions please read sales brochure carefully before concluding a sale. *Condition apply

NEW INDIA ASSURANCE
दि न्यू इन्डिया एश्योरन्स कंपनी लिमिटेड
The New India Assurance Co. Ltd

www.newindia.co.in
Toll free 1800-209-1415

Regd & Head Office:
New India Assurance Bldg., 87, M.G. Road, Fort, Mumbai-400 001, INDIA

IRDAI REGN. No. 190 CIN : U 99999 MH 1919 GOI 000 526 UIN.IRDAN190P0129V01100001 URN No. : NIA/16-17/PC/292

DIRECTORS & OFFICERS LIABILITY

D & O Insurance policies offer liability cover for company managers to protect them from claims which may arise from the decisions and actions taken within the scope of their regular duties.

For more details on risk factors, terms & conditions please read sales brochure carefully before concluding a sale. *Condition apply

NEW INDIA ASSURANCE
दि न्यू इन्डिया एश्योरन्स कंपनी लिमिटेड
The New India Assurance Co. Ltd

www.newindia.co.in
Toll free 1800-209-1415

Regd & Head Office:
New India Assurance Bldg., 87, M.G. Road, Fort, Mumbai-400 001, INDIA

IRDAI REGN. No. 190 CIN : U 99999 MH 1919 GOI 000 526 UIN.IRDAN190P0072V01100001 URN No. : NIA/16-17/PC/292

The newly launched Elantra is the only car in its segment with a basket price lower than Rs 2 lakh.

## EXECUTIVE SEDANS

| | CHEVROLET CRUZE | HYUNDAI ELANTRA PETROL | HYUNDAI ELANTRA DIESEL | SKODA OCTAVIA PETROL 1.4 | SKODA OCTAVIA PETROL 1.8 | SKODA OCTAVIA DIESEL | TOYOTA COROLLA ALTIS PETROL | TOYOTA COROLLA ALTIS DIESEL | VW JETTA PETROL | VW JETTA DIESEL |
|---|---|---|---|---|---|---|---|---|---|---|
| **SERVICE PARTS** | | | | | | | | | | |
| Air Filter | 982 | 706 | 953 | 839 | 900 | 900 | 1013 | 1330 | 1348 | 1348 |
| Oil Filter | 3160 | 219 | 459 | 501 | 1221 | 400 | 562 | 562 | 420 | 670 |
| Fuel Filter | 2261 | 1238 | 2050 | NA | NA | 2207 | 3575 | 2741 | 2019 | 1834 |
| Wiper Blades (pair) | 1958 | 1521 | 1521 | 2729 | 2729 | 2729 | 1450 | 1450 | 2697 | 2755 |
| Spark Plug (for entire set) | NA | 2996 | NA | 1665 | 2404 | NA | 1344 | N/A | 4140 | NA |
| Timing Belt/ Chain | 4159 | 4351 | 3701 | 3626 | 9900 | 5557 | 7021 | 3090 | 7505 | 5865 |
| Fan Belt/ Drivebelt | 3249 | 1459 | 1399 | 774 | 2074 | 898 | 3885 | 2793 | 2638 | 976 |
| Front Brake Pads (set of 4) | 12580 | 4599 | 4599 | 6576 | 5034 | 6576 | 4985 | 8056 | 5767 | 5767 |
| **MECHANICAL PARTS** | | | | | | | | | | |
| A/c Evaporator Coil | 16181 | 11798 | 11798 | 30000 | 30000 | 13322 | 34840 | 12954 | 23151 | 15254 |
| Radiator Hose Set | 2817 | 1318 | 2852 | 6409 | 6409 | 6409 | 1861 | 2247 | 2931 | 3503 |
| Front Strut/ Shock Absorber | 6794 | 5752 | 5752 | 8591 | 9065 | 5067 | 4133 | 5839 | 8836 | 8836 |
| Front Brake Disc/ Drum | 5395 | 4482 | 4482 | 4564 | 5517 | 4564 | 5940 | 5940 | 3866 | 3866 |
| Front Suspension Lower Arm | 12720 | 5998 | 5998 | 6504 | 6504 | 6504 | 11659 | 11659 | 7680 | 7680 |
| Clutch and Pressure Plate | 17023 | 10178 | 10534 | 12183 | NA | 12183 | 13660 | 16131 | 7690 | NA |
| Clutch Release Bearing | 11522 | 1317 | 1317 | 2250 | NA | 3910 | 2059 | 2059 | 1710 | NA |
| **ACCIDENT REPAIR PARTS** | | | | | | | | | | |
| Front bumper | 16769 | 8695 | 8695 | 11609 | 11609 | 11609 | 9258 | 9738 | 16100 | 16100 |
| Wheel rim (each) | 15067 | 14696 | 14696 | 5667 | 6941 | 6941 | 20485 | 20485 | 1792 | 1792 |
| Front fender | 8660 | 7586 | 7586 | 9374 | 9374 | 9374 | 11626 | 11626 | 9192 | 9192 |
| Bonnet | 21808 | 15869 | 15869 | 20333 | 20333 | 20333 | 18488 | 18488 | 17651 | 17651 |
| Radiator | 11518 | 10967 | 14156 | 10274 | 10274 | 10274 | 11432 | 11328 | 15714 | 12422 |
| Front door | 23450 | 18265 | 18265 | 22316 | 22316 | 22316 | 30582 | 30582 | 23000 | 23000 |
| Bootlid/ tailgate | 18454 | 16896 | 16896 | 34523 | 34523 | 34523 | 21576 | 21576 | 35000 | 35000 |
| Headlight Assy. (each with bulb) | 10508 | 13448 | 13448 | 13617 | 25567 | 10739 | 20471 | 20471 | 10456 | 10456 |
| Tail-light Assy. (each with bulb) | 7815 | 4823 | 4823 | 9711 | 9711 | 9711 | 9504 | 9504 | 8588 | 8588 |
| Front windscreen glass | 10385 | 18478 | 18478 | 17786 | 17797 | 17786 | 8936 | 8936 | 19342 | 19342 |
| Side mirror (with casing) | 14806 | 7773 | 7773 | 3210 | 3210 | 3210 | 11263 | 11263 | 3210 | 3210 |
| Total Price Basket | 260041 | 195428 | 198100 | 245631 | 253412 | 228042 | 271603 | 250842 | 242443 | 215107 |
| Vehicle price (ex showroom Mumbai, base version) | 1478231 | 1374213 | 1564688 | 1628428 | 1984092 | 1790333 | 1457267 | 1565933 | 1512234 | 1633020 |
| Percentage of parts to car price | 17.6% | 14.2% | 12.7% | 15.1% | 12.8% | 12.7% | 18.6% | 16.0% | 16.0% | 13.2% |




NEW INDIA FLOATER MEDICLAIM

• Single floater sum insured for entire family.
• Hospitalisation benefit for floater Sum Insured of ₹ 2 lakhs, ₹ 3 lakhs, ₹ 5 lakhs & ₹ 8 lakhs.

For more details on risk factors, terms & conditions please read sales brochure carefully before concluding a sale. *Condition apply

NEW INDIA ASSURANCE
दि न्यू इन्डिया एश्योरन्स कंपनी लिमिटेड
The New India Assurance Co. Ltd

www.newindia.co.in
Toll free 1800-209-1415
Regd & Head Office:
New India Assurance Bldg., 87, M.G. Road, Fort, Mumbai-400 001, INDIA

IRDAI REGN. No. 190 CIN : U 99999 MH 1919 GOI 000 526 UIN No. NIAHLIP13030V011213 URN No. : NIA/16-17/PC/292

← The Verna is available in 1.4-litre and 1.6-litre engines for both petrol and diesel variants, and the cost of spares for different capacity engines running on the same fuel are the same. Thus, ownership costs between a 1.4-litre and a 1.6-litre Verna will change largely due to the varying fuel consumption.

VW, once again, charges the most for its spare parts. The price basket for the Vento diesel is 62 percent more expensive than that of the Ciaz diesel. In fact, the Ventos will be heavier on your pocket than their peers in terms of service, mechanical and accident repair parts. It is interesting to note that the basket price for the Skoda Rapid, though high, is lower than that of the Vento, even though they are essentially the same cars. The principal difference in their basket prices stems from the lower prices for the Rapid's accident repair parts.

The Honda City, arguably the most popular car in this segment, is 15 percent more expensive than the Ciaz on average in terms of basket price.

> "The Jetta's relatively cheap price basket comes as a pleasant surprise."

### EXECUTIVE SEDANS

The new Hyundai Elantra boasts the lowest basket price here, though the Renault Fluence, Skoda Octavia diesel and VW Jetta diesel feature adequately (and relatively) low basket prices too.

The most expensive basket is for the VW Jetta petrol. It is notable that for all VW Group cars here, namely the Jettas and Octavias, the diesels feature a lower basket price as compared to the petrols.

The Chevrolet Cruze will drain your pocket when it comes to service parts and mechanical parts – its brake pads cost Rs 12,580 as compared to Rs 4,599 for the Elantra and its oil filter is a pricy Rs 3,160 as compared to the Elantra's Rs 219. The most expensive accident parts, however, belong to the Jettas – the bootlid costs a whopping Rs 35,000 as compared to Rs 16,896 for the Elantras.

On a side note, you might want to take extra care of the front door if you own a Toyota Corolla Altis. At Rs 30,582, a single Altis front door costs as much as the Maruti Alto 800's entire spare parts basket.

### PREMIUM EXECUTIVE SEDAN

The premium executive sedan segment is a relatively small segment, consisting of just three cars. In descending order of affordability of the spare parts basket, they are the Skoda Superb, the Toyota Camry Hybrid and the regular Toyota Camry. While the service parts for all three cost more or less the same and the →

## PREMIUM EXECUTIVE SEDANS

| | SKODA SUPERB PETROL | TOYOTA CAMRY | TOYOTA CAMRY HYBRID |
|---|---|---|---|
| **SERVICE PARTS** | | | |
| Air Filter | 900 | 1302 | 1550 |
| Oil Filter | 1221 | 770 | 562 |
| Fuel Filter | NA | 2784 | 4916 |
| Wiper Blades (pair) | 3830 | 4469 | 4502 |
| Spark Plug (for entire set) | 1665 | 1144 | 1144 |
| Timing Belt/ Chain | 9900 | 2827 | 2827 |
| Fan Belt/ Drivebelt | 2074 | 5075 | 2990 |
| Front Brake Pads (set of 4) | 5034 | 5956 | 6256 |
| **MECHANICAL PARTS** | | | |
| A/c Evaporator Coil | 27788 | 34973 | 27963 |
| Radiator Hose Set | 5244 | 2349 | 1960 |
| Front Strut/ Shock Absorber | 11000 | 13518 | 10210 |
| Front Brake Disc/ Drum | 5517 | 6212 | 6212 |
| Front Suspension Lower Arm | 15230 | 11657 | 11657 |
| Clutch and Pressure Plate | 30011 | 12665 | 12665 |
| Clutch Release Bearing | 3910 | 1399 | 1399 |
| **ACCIDENT REPAIR PARTS** | | | |
| Front bumper | 31500 | 11765 | 11095 |
| Wheel rim (each) | 21000 | 42460 | 42153 |
| Front fender | 13158 | 13987 | 13897 |
| Bonnet | 26000 | 29814 | 27910 |
| Radiator | 12000 | 44292 | 50241 |
| Front door | 28000 | 40933 | 42165 |
| Bootlid/ tailgate | 37000 | 32610 | 31126 |
| Headlight Assy. (each with bulb) | 42000 | 44581 | 35610 |
| Tail-light Assy. (each with bulb) | 10853 | 12328 | 12328 |
| Front windscreen glass | 23636 | 39789 | 46176 |
| Side mirror (with casing) | 17867 | 21777 | 21908 |
| Total Price Basket | 386338 | 441429 | 431415 |
| Vehicle price (ex showroom Mumbai, base version) | 2506725 | 3215278 | 3522216 |
| Percentage of parts to car price | 15.4% | 13.7% | 12.2% |



Of the three premium executive sedans, the Superb has the lowest-priced spares.

NEW INDIA TOP UP MEDI-CLAIM

Future Without Fear...
Total Cover Upto 30 Lacs | Tax Benefit* 80D | Hospital Cash
Get Well Benefit | 74+Day Care Procedure | Covers Entire Family

For more details on risk factors, terms & conditions please read sales brochure carefully before concluding a sale. *Condition apply

NEW INDIA ASSURANCE
दि न्यू इन्डिया एश्योरन्स कंपनी लिमिटेड
The New India Assurance Co. Ltd

www.newindia.co.in
Toll free 1800-209-1415
Regd & Head Office:
New India Assurance Bldg., 87, M.G. Road, Fort, Mumbai-400 001, INDIA

IRDAI REGN. No. 190 CIN : U 99999 MH 1919 GOI 000 526 UIN. NIAHLIP15004V011415. URN No. : NIA/16-17/PC/292

← mechanical parts for the Camrys are actually cheaper than that of the Superb, the gap in basket price appears when you look at the accident repair parts – the Camrys' accident repair parts are priced at nearly a 30 percent premium over those of the Superb.

However, it is worth noting that the Superb will set you back more when it comes to the clutch and pressure plate, clutch-release bearing and front bumper – all of which cost about three times Camrys' parts.

Uncharacteristically, Maruti loses its low-price supremacy with the Brezza against the Ecosport diesel.

## COMPACT SUVS

The spare part prices for the compact SUV segment reveal a drastic departure from the trends we have been witnessing until now. Slotting in with the lowest basket price is the Mahindra KUV100, and topping the segment off with the highest basket price is again a Mahindra – the NuvoSport.

For the first time, Maruti and Ford have lost the supremacy in terms of spare parts affordability – the Vitara Brezza and the EcoSport are both only about 10 percent cheaper than the NuvoSport in basket price terms.

> "The 1.6 S-Cross has a 35 percent costlier price basket than the 1.3 S-Cross."

The Vitara Brezza's service parts, specifically the oil and fuel filters, are surprisingly pricey compared to all other rivals in this segment. It also displays a higher-than-usual →

| COMPACT SUVS | FORD ECOSPORT PETROL | FORD ECOSPORT DIESEL | MAHINDRA KUV100 PETROL | MAHINDRA KUV100 DIESEL | MAHINDRA NUVOSPORT | MAHINDRA TUV 300 | MARUTI VITARA BREZZA |
|---|---|---|---|---|---|---|---|
| **SERVICE PARTS** | | | | | | | |
| Air Filter | 226 | 226 | 385 | 385 | 611 | 642 | 345 |
| Oil Filter | 90 | 399 | 185 | 185 | 185 | 185 | 390 |
| Fuel Filter | 822 | 1406 | 310 | 595 | 595 | 595 | 1660 |
| Wiper Blades (pair) | 780 | 780 | 415 | 415 | 539 | 245 | 520 |
| Spark Plug (for entire set) | 776 | NA | 400 | NA | NA | NA | NA |
| Timing Belt/ Chain | 631 | 1238 | 775 | 1275 | 1290 | 1290 | 1160 |
| Fan Belt/ Drivebelt | 150 | 462 | 350 | 435 | 956 | 665 | 420 |
| Front Brake Pads (set of 4) | 3725 | 3725 | 1549 | 1549 | 3595 | 2945 | 2750 |
| **MECHANICAL PARTS** | | | | | | | |
| A/c Evaporator Coil | 4786 | 4786 | 3100 | 3100 | 1324 | 6800 | 4200 |
| Radiator Hose Set | 1235 | 764 | 225 | 210 | 356 | 251 | 780 |
| Front Strut/ Shock Absorber | 2395 | 2395 | 1400 | 1400 | 1863 | 1990 | 2400 |
| Front Brake Disc/ Drum | 1501 | 1501 | 1100 | 1100 | 2416 | 2473 | 1390 |
| Front Suspension Lower Arm | 1872 | 1872 | 1500 | 1500 | 5095 | 5095 | 1475 |
| Clutch and Pressure Plate | 9010 | 3605 | 3100 | 3200 | 4484 | 4350 | 3088 |
| Clutch Release Bearing | 1702 | 1702 | 550 | 550 | 3990 | 1216 | 3137 |
| **ACCIDENT REPAIR PARTS** | | | | | | | |
| Front bumper | 1900 | 1900 | 3990 | 3990 | 3978 | 3150 | 3100 |
| Wheel rim (each) | 1501 | 1501 | 1005 | 1005 | 2776 | 1900 | 1500 |
| Front fender | 1497 | 1497 | 1650 | 1650 | 2142 | 2800 | 1825 |
| Bonnet | 8977 | 8977 | 4500 | 4500 | 8262 | 7700 | 6870 |
| Radiator | 4310 | 4310 | 3378 | 3790 | 4955 | 4955 | 4830 |
| Front door | 6973 | 6973 | 5100 | 5100 | 10200 | 10100 | 9030 |
| Bootlid/ tailgate | 9009 | 9009 | 2100 | 2100 | 11600 | 11530 | 9040 |
| Headlight Assy. (each with bulb) | 4313 | 4313 | 2690 | 2690 | 3809 | 3807 | 4700 |
| Tail-light Assy. (each with bulb) | 1655 | 1655 | 1650 | 1650 | 1150 | 1150 | 2820 |
| Front windscreen glass | 4280 | 4280 | 2900 | 2900 | 5171 | 4200 | 4270 |
| Side mirror (with casing) | 2567 | 2567 | 1200 | 1200 | 415 | 1460 | 1950 |
| **Total Price Basket** | 76683 | 71843 | 45507 | 46474 | 81757 | 81494 | 73650 |
| Vehicle price (ex showroom Mumbai, base version) | 731049 | 807582 | 482731 | 580282 | 790578 | 771667 | 763686 |
| Percentage of parts to car price | 10.5% | 8.9% | 9.4% | 8.0% | 10.3% | 10.6% | 9.6% |




## MID-SIZE SUVS

| MID-SIZE SUVS | HONDA BR-V PETROL | HONDA BR-V DIESEL | HYUNDAI CRETA PETROL | HYUNDAI CRETA 1.4 DIESEL | HYUNDAI CRETA 1.6 DIESEL | MAHINDRA SCORPIO S4 | MAHINDRA SCORPIO S2 | MAHINDRA XUV500 | MARUTI S-CROSS 1.3 | MARUTI S-CROSS 1.6 | NISSAN TERRANO DIESEL | RENAULT DUSTER PETROL | RENAULT DUSTER DIESEL | TATA SAFARI STORME |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **SERVICE PARTS** | | | | | | | | | | | | | | |
| Air Filter | 482 | 295 | 321 | 346 | 346 | 642 | 642 | 995 | 280 | 910 | 398 | 435 | 855 | 793 |
| Oil Filter | 166 | 425 | 219 | 459 | 459 | 209 | 209 | 209 | 390 | 830 | 370 | 261 | 541 | 250 |
| Fuel Filter | 507 | 1320 | 860 | 2050 | 2050 | 1595 | 248 | 1595 | 1254 | 1254 | 1640 | NA | 1598 | 2351 |
| Wiper Blades (pair) | 986 | 986 | 533 | 533 | 533 | 700 | 700 | 1122 | 475 | 475 | 366 | 653 | 653 | 776 |
| Spark Plug (for entire set) | 1600 | NA | 1128 | NA | NA | NA | NA | NA | NA | NA | NA | 684 | NA | NA |
| Timing Belt/ Chain | 800 | 1185 | 2927 | 798 | 798 | 1826 | 2822 | 1826 | 1160 | 2780 | 1897 | 3006 | 1897 | 2085 |
| Fan Belt/ Drivebelt | 450 | 400 | 699 | 377 | 377 | 925 | 956 | 1395 | 420 | 1100 | 1221 | 1542 | 1221 | 656 |
| Front Brake Pads (set of 4) | 4083 | 3600 | 3775 | 3775 | 3775 | 4386 | 4180 | 4995 | 2750 | 2750 | 3334 | 3334 | 3334 | 3441 |
| **MECHANICAL PARTS** | | | | | | | | | | | | | | |
| A/c Evaporator Coil | 1770 | 1770 | 5899 | 5899 | 5899 | 7490 | 7490 | 8155 | 4200 | 4200 | 5767 | 5390 | 5390 | 3349 |
| Radiator Hose Set | 420 | 420 | 1111 | 1097 | 1097 | 346 | 376 | 876 | 395 | 530 | 3251 | 3320 | 2567 | 433 |
| Front Strut/ Shock Absorber | 1884 | 1884 | 3099 | 3099 | 3099 | 2397 | 1389 | 4073 | 3450 | 3450 | 3582 | 3582 | 3582 | 3375 |
| Front Brake Disc/ Drum | 3200 | 3200 | 3299 | 3299 | 3299 | 2851 | 2196 | 3380 | 1390 | 1390 | 3300 | 3300 | 3300 | 2602 |
| Front Suspension Lower Arm | 2300 | 2300 | 2359 | 2359 | 2359 | 5441 | 4865 | 5995 | 1475 | 1475 | 5284 | 5284 | 5284 | 1945 |
| Clutch and Pressure Plate | 2639 | 8950 | 5248 | 6621 | 6621 | 7358 | 5253 | 10200 | 3088 | 11405 | 11664 | 8313 | 11664 | 13151 |
| Clutch Release Bearing | 700 | 1300 | 1317 | 1317 | 1317 | 3700 | 1250 | 4113 | 3137 | 3137 | 2068 | 2068 | 3332 | NA |
| **ACCIDENT REPAIR PARTS** | | | | | | | | | | | | | | |
| Front bumper | 2814 | 2814 | 1628 | 1628 | 1628 | 5100 | 5100 | 6090 | 4290 | 4290 | 7170 | 7162 | 7162 | 4956 |
| Wheel rim (each) | 1650 | 1650 | 1699 | 1699 | 1699 | 2958 | 3090 | 3672 | 1500 | 2050 | 3990 | 3205 | 3205 | 2548 |
| Front fender | 1908 | 1908 | 1886 | 1886 | 1886 | 3600 | 3600 | 6018 | 2000 | 2000 | 5300 | 5671 | 5671 | 3771 |
| Bonnet | 4621 | 4621 | 6996 | 6996 | 6996 | 8970 | 8970 | 9690 | 6750 | 6750 | 11986 | 16628 | 16628 | 8740 |
| Radiator | 4898 | 5464 | 3985 | 3985 | 3985 | 7995 | 7604 | 8900 | 5000 | 15360 | 3375 | 7139 | 7139 | 7836 |
| Front door | 6080 | 6080 | 12979 | 12979 | 12979 | 10400 | 10400 | 10670 | 8400 | 8400 | 15645 | 17000 | 17000 | 13489 |
| Bootlid/ tailgate | 12403 | 12403 | 9199 | 9199 | 9199 | 13265 | 13265 | 14849 | 8000 | 8000 | 13335 | 17666 | 17666 | 17076 |
| Headlight Assy. (each with bulb) | 12000 | 12000 | 4985 | 4985 | 4985 | 5900 | 4924 | 12669 | 4394 | 4394 | 6950 | 6733 | 6733 | 8695 |
| Tail-light Assy. (each with bulb) | 3580 | 3580 | 2276 | 2276 | 2276 | 1699 | 1699 | 3876 | 2645 | 2645 | 3148 | 3601 | 3601 | 1607 |
| Front windscreen glass | 4500 | 4500 | 4585 | 4585 | 4585 | 6242 | 4916 | 7038 | 4800 | 4800 | 4874 | 5020 | 5020 | 6823 |
| Side mirror (with casing) | 2031 | 2031 | 1999 | 1999 | 1999 | 1884 | 1690 | 6106 | 2800 | 4700 | 1410 | 1625 | 1625 | 4785 |
| **Total Price Basket** | 78472 | 85086 | 85011 | 84246 | 84246 | 107879 | 97834 | 138507 | 74443 | 99075 | 121325 | 132622 | 136668 | 115533 |
| Vehicle price (ex showroom Mumbai, base version) | 940867 | 1058350 | 975529 | 1063177 | 1315654 | 977668 | 1036191 | 1229284 | 859768 | 1091381 | 1023136 | 890241 | 971634 | 1101393 |
| Percentage of parts to car price | 8.3% | 8.0% | 8.7% | 7.9% | 6.4% | 11.0% | 9.4% | 11.3% | 8.7% | 9.1% | 11.9% | 14.9% | 14.1% | 10.5% |




NEW INDIA GRIHA SUVIDHA POLICY
Starting as low as ₹3/- per day only
NO LIST - NO BILL of items are required
For more details on risk factors, terms & conditions please read sales brochure carefully before concluding a sale.
*Condition apply
NEW INDIA ASSURANCE
दि न्यू इन्डिया एश्योरन्स कंपनी लिमिटेड
The New India Assurance Co. Ltd
www.newindia.co.in
Toll free 1800-209-1415
Regd & Head Office: New India Assurance Bldg., 87, M.G. Road, Fort, Mumbai-400 001, INDIA
IRDAI REGN. No. 190 CIN : U 99999 MH 1919 GOI 000 526 UIN No : IRDAN190P0001V01201516 URN No. : NIA/16-17/PC/292

NEW INDIA's
FOR THE FIRST TIME IN INDIA
LONG TERM TWO WHEELER PACKAGE POLICY
SAVE UPTO 50% ON YOUR 3 YEARS TWO-WHEELER INSURANCE
PAY ONCE AND GET PEACE OF MIND FOR 3 YEARS
For more details on risk factors, terms & conditions please read sales brochure carefully before concluding a sale.
*Condition apply
NEW INDIA ASSURANCE
दि न्यू इन्डिया एश्योरन्स कंपनी लिमिटेड
The New India Assurance Co. Ltd
www.newindia.co.in
Toll free 1800-209-1415
Regd & Head Office: New India Assurance Bldg., 87, M.G. Road, Fort, Mumbai-400 001, INDIA
IRDAI REGN. No. 190 CIN : U 99999 MH 1919 GOI 000 526 UIN: IRDAN190P0003V01201415 URN No. : NIA/16-17/PC/292

Lodgy spares cost nearly twice as much as the Ertiga's.

← price for accident repair parts. Also, notably expensive are the headlight assemblies for the EcoSport and Vitara Brezza.

## MID-SIZE SUV

Mahindra once again offers the most expensive basket price, with the XUV500, while Maruti is back as the manufacturer with the most affordable basket price with the S-Cross 1.3. The mid-size SUV segment is the first one in which Honda has shown price competitiveness, with the seven-seater Honda BR-V that takes on the Hyundai Creta in terms of basket price.

The Renault Duster's basket price is nearly as high as the XUV500's. Surprisingly, its badge-engineered, slightly-more-premium sibling, the Terrano, features a lower basket price, mainly on account of cheaper accident repair parts.

In fact, the Duster's front door and tailgate are the most expensive in this segment, costing nearly thrice as much as the BR-V's. Another interesting observation is the nearly 35 percent difference in the basket price of the 1.3-litre and 1.6-litre Maruti S-Cross. Unlike in the Creta, the bigger engine in the S-Cross does drive up costs, principally on account of more expensive service parts, clutch and pressure plate, and radiator.

The Tata Safari Storme is not very competitive either, with a basket price nearly 20 percent higher than its most direct competitor, the Mahindra Scorpio. It is also interesting that the Hyundai Creta diesels feature lower basket prices, on account of lower service costs, as compared to the Creta petrol.

## MPVS

| MPVS | CHEVROLET ENJOY PETROL | CHEVROLET ENJOY DIESEL | DATSUN GO + | HONDA MOBILIO PETROL | HONDA MOBILIO DIESEL | MAHINDRA BOLERO | MAHINDRA XYLO | MARUTI OMNI | MARUTI EECO | MARUTI ERTIGA PETROL | MARUTI ERTIGA DIESEL | RENAULT LODGY | TATA SUMO GOLD | TOYOTA INNOVA CRYSTA 2.4 | TOYOTA INNOVA CRYSTA 2.8 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| **SERVICE PARTS** | | | | | | | | | | | | | | | |
| Air Filter | 268 | 278 | 232 | 482 | 295 | 447 | 611 | 520 | 240 | 305 | 259 | 600 | 925 | 1787 | 1810 |
| Oil Filter | 131 | 453 | 175 | 166 | 425 | 209 | 209 | 90 | 90 | 90 | 390 | 541 | 339 | 444 | 444 |
| Fuel Filter | 554 | 1518 | NA | 507 | 1320 | 595 | 1595 | 325 | 299 | 478 | 1254 | 2567 | 1863 | 1772 | 2290 |
| Wiper Blades (pair) | 1103 | 1103 | 295 | 886 | 886 | 496 | 590 | 230 | 340 | 432 | 432 | 828 | 306 | 897 | 4234 |
| Spark Plug (for entire set) | 660 | NA | 125 | 1600 | NA | NA | NA | 195 | 448 | 780 | NA | NA | NA | NA | NA |
| Timing Belt/ Chain | 1561 | 1501 | 1190 | 800 | 1185 | 325 | 3203 | 830 | 775 | 631 | 1160 | 1897 | NA | 2696 | 2296 |
| Fan Belt/ Drivebelt | 174 | 449 | 1214 | 450 | 400 | 325 | 1056 | 95 | 140 | 240 | 470 | 1221 | 481 | 4221 | 5291 |
| Front Brake Pads (set of 4) | 1824 | 1824 | 2306 | 3299 | 3299 | 1995 | 3448 | 564 | 1050 | 3239 | 3239 | 3753 | 2067 | 5019 | 5993 |
| **MECHANICAL PARTS** | | | | | | | | | | | | | | | |
| A/c Evaporator Coil | 5170 | 5170 | 3971 | 1770 | 1770 | 3045 | 7135 | NA | 2610 | 1900 | 1900 | 4857 | 8222 | 12298 | 12954 |
| Radiator Hose Set | 321 | 410 | 450 | 420 | 420 | 267 | 338 | 147 | 228 | 129 | 194 | 3251 | 546 | 979 | 1697 |
| Front Strut/ Shock Absorber | 2345 | 2345 | 1691 | 2100 | 2100 | 1260 | 1527 | 2585 | 1740 | 1796 | 1796 | 1955 | 1777 | 3609 | 7271 |
| Front Brake Disc/ Drum | 2115 | 2115 | 930 | 1906 | 1906 | 1690 | 2448 | 550 | 855 | 1793 | 1793 | 7896 | 1261 | 6211 | 6211 |
| Front Suspension Lower Arm | 2880 | 2880 | 1289 | 2443 | 2443 | 1679 | 4889 | 383 | 477 | 2380 | 2380 | 3579 | 3172 | 5906 | 5906 |
| Clutch and Pressure Plate | 3105 | 3492 | 2974 | 2639 | 8950 | 5253 | 5247 | 1361 | 1825 | 3345 | 3088 | 11664 | 8696 | 9198 | 13075 |
| Clutch Release Bearing | 1242 | 2287 | NA | 700 | 1300 | 1295 | 1306 | 510 | 895 | 3137 | 3137 | 3332 | 929 | 4558 | 4632 |
| **ACCIDENT REPAIR PARTS** | | | | | | | | | | | | | | | |
| Front bumper | 1815 | 1815 | 1490 | 2700 | 2700 | 3850 | 4809 | 890 | 1150 | 1625 | 1625 | 2482 | 3101 | 6300 | 9282 |
| Wheel rim (each) | 1849 | 1849 | 950 | 2010 | 2010 | 2700 | 2958 | 890 | 865 | 1680 | 1680 | 1698 | 2050 | 19765 | 17822 |
| Front fender | 1708 | 1708 | 1295 | 1800 | 1800 | 2995 | 2142 | 4272* | 986 | 1617 | 1617 | 3390 | 2942 | 4408 | 4006 |
| Bonnet | 6194 | 6194 | 4200 | 3277 | 3277 | 8188 | 8262 | NA | 2968 | 6002 | 6002 | 10600 | 4335 | 9512 | 11060 |
| Radiator | 3851 | 4407 | 2490 | 7327 | 4100 | 4900 | 6344 | 2300 | 3009 | 4013 | 3600 | 3375 | 5563 | 11259 | 13558 |
| Front door | 12250 | 12250 | 6980 | 10826 | 10826 | 9180 | 10195 | 3932 | 4956 | 8845 | 8845 | 13800 | 6119 | 24561 | 25301 |
| Bootlid/ tailgate | 11473 | 11473 | 6716 | 13500 | 13500 | 10302 | 9000 | 5637 | 4904 | 10646 | 10646 | 13490 | 5688 | 14702 | 14703 |
| Headlight Assy. (each with bulb) | 2822 | 2822 | 2720 | 3021 | 3021 | 3999 | 3995 | 453 | 2644 | 2755 | 2755 | 10563 | 3115 | 5911 | 10162 |
| Tail-light Assy. (each with bulb) | 1230 | 1230 | 1110 | 2258 | 2258 | 899 | 1536 | 371 | 773 | 1276 | 1276 | 6854 | 794 | 3706 | 3786 |
| Front windscreen glass | 5018 | 5018 | 3895 | 3000 | 3000 | 4141 | 5171 | 2305 | 3422 | 4898 | 4898 | 4772 | 4040 | 9538 | 8914 |
| Side mirror (with casing) | 1625 | 1625 | 768 | 2550 | 2550 | 215 | 1680 | 220 | 60 | 2112 | 2112 | 1862 | 1482 | 5839 | 6263 |
| Total Price Basket | 73288 | 76216 | 49456 | 72437 | 75741 | 70250 | 89694 | 29655 | 37749 | 66144 | 66548 | 120827 | 69813 | 175092 | 198957 |
| Vehicle price (ex showroom Mumbai, base version) | 690605 | 835133 | 413825 | 773098 | 931734 | 698972 | 872845 | 288981 | 352789 | 681368 | 821395 | 846881 | 721744 | 1471255 | 1698020 |
| Percentage of parts to car price | 10.6% | 9.1% | 12.0% | 9.4% | 8.1% | 10.1% | 10.3% | 10.3% | 10.7% | 9.7% | 8.1% | 14.3% | 9.7% | 11.9% | 11.7% |

*Front panel assembly




## PREMIUM SUVS

The lowest basket price here belongs to the Hyundai Santa Fe, despite being the priciest car in the segment. The price of its service parts is more or less equal to that of the Elantra.

In fact, the Renault Koleos aside, all SUVs in this segment feature roughly similar prices for service parts as well as mechanical parts; the major differences are in the accident repair parts – these vary widely, from Rs 1,76,251 for the Rexton to Rs 2,52,557 for the Endeavour.

The Rexton, though cheapest on the whole, features the most expensive AC evaporator coil in this survey at Rs 39,303.

The Skoda Yeti and Ford Endeavour are also expensive in terms of the basket price, mainly on account of expensive accident repair parts, especially the headlight assemblies.

## MPVS

The MPV segment ranges from the humble Omni to the popular Innova Crysta. As such, it is advisable to consider them in smaller groups.

> "The Omni holds the distinction of having the lowest-priced spare basket in this study."



At the bottom of the MPV segment are the Maruti Omni and Maruti Eeco. The Omni features the lowest basket price in this survey, but then again, it is one of the cheapest and most rudimentary cars in the market today. The Maruti Eeco is not too far behind, and features one of the cheapest components in the entire survey – Rs 60 for the side mirror. →

PRIVATE CAR PACKAGE POLICY
• Loss or damage to the vehicle insured
• Personal Accident cover for Owner-driver
• No- claim discounts ranging from 20% to 50%
For more details on risk factors, terms & conditions please read sales brochure carefully before concluding a sale. *Condition apply
NEW INDIA ASSURANCE
दि न्यू इन्डिया एश्योरन्स कंपनी लिमिटेड
The New India Assurance Co. Ltd
www.newindia.co.in
Toll free 1800-209-1415
Regd & Head Office: New India Assurance Bldg., 87, M.G. Road, Fort, Mumbai-400 001, INDIA
IRDAI REGN. No. 190 CIN : U 99999 MH 1919 GOI 000 526 UIN. IRDAN190P0042V01100001 URN No. : NIA/16-17/PC/292

STUDENTS SAFETY INSURANCE POLICY
• Add on OPD cover
• Add on Hospitalisation cover
• Add on cover for parents/teaching/non teaching staff
• Basic Personal Accident upto ₹ 5 lacs sum insured per student
For more details on risk factors, terms & conditions please read sales brochure carefully before concluding a sale. *Condition apply
NEW INDIA ASSURANCE
दि न्यू इन्डिया एश्योरन्स कंपनी लिमिटेड
The New India Assurance Co. Ltd
www.newindia.co.in
Toll free 1800-209-1415
Regd & Head Office: New India Assurance Bldg., 87, M.G. Road, Fort, Mumbai-400 001, INDIA
IRDAI REGN. No. 190 CIN : U 99999 MH 1919 GOI 000 526 UIN. IRDAN190P0004V01201314 URN No. : NIA/16-17/PC/292

← Above these entry-level people movers sit the Mahindra Bolero and Tata Sumo Gold. The basket prices for both are similar, though the Sumo Gold's service as well as mechanical parts are more expensive than the Bolero's. Where the Sumo Gold wins is in its lower-priced accident repair parts.

Then come the Chevrolet Enjoy, Maruti Ertiga, Honda Mobilio, Mahindra Xylo and Renault Lodgy. Of these, the Ertiga offers the lowest basket price. Its service part prices are the lowest, and so are those for the mechanical (except for the Mobilio petrol) and accident repair parts. Noteworthy here is the exceptionally high basket price of the Renault Lodgy. At Rs 1,20,827, it is almost twice that of the Ertiga. The Lodgy's mechanical as well as accident repair parts are exceptionally expensive, owing to a pricey clutch and pressure plate, headlight and tail-light assembly.

At the top of this segment is the Toyota Innova Crysta. Not only is it nearly twice as expensive as its MPV cousins to buy, it is that much more expensive to own too. Notably expensive are its clutch and pressure plates and body panels.

Despite being the priciest premium SUV, the Santa Fe has the lowest price basket.

## LUXURY CARS

All luxury car manufacturers, except Volvo, refused to participate in our 2016 *Spare Parts Survey*. We can only assume that this is because they are reluctant to publicly reveal the prices of the spare parts, which further leads us to believe that these are prohibitively high. Many luxury car manufacturers also shied away from this survey citing its conflict with the promotion of their service packages.

Provided here is Volvo's spare parts list for your reference, though we understand that as a standalone, it might not be too useful. In any case, it can serve as a rough indication of what luxury cars in the corresponding segment might cost in terms of spare parts. AI

Volvo was the only luxury brand brave enough to participate in this survey.

## PREMIUM SUVS

| | CHEVROLET TRAILBLAZER | FORD ENDEAVOUR 2.2 | FORD ENDEAVOUR 3.2 AUTOMATIC | HONDA CR-V 2.0 | HONDA CR-V 2.4 | HYUNDAI SANTA FE | HYUNDAI SANTA FE 4X4 | SSANGYONG REXTON | SKODA YETI |
|---|---|---|---|---|---|---|---|---|---|
| **SERVICE PARTS** | | | | | | | | | |
| Air Filter | 1600 | 1513 | 1513 | 482 | 482 | 819 | 819 | 1395 | 1210 |
| Oil Filter | 600 | 449 | 449 | 166 | 166 | 499 | 499 | 415 | 420 |
| Fuel Filter | 1400 | 1324 | 1324 | 1835 | 1835 | 1376 | 1376 | 2100 | 1971 |
| Wiper Blades (pair) | 2950 | 1565 | 1565 | 1809 | 1809 | 1968 | 1968 | 1345 | 2405 |
| Spark Plug (for entire set) | NA | NA | NA | 3844 | 3844 | NA | NA | NA | NA |
| Timing Belt/ Chain | 3500 | 5197 | 5197 | 3133 | 3133 | 2214 | 2214 | 8800 | 2980 |
| Fan Belt/ Drivebelt | 1900 | 3804 | 3804 | 1862 | 1862 | 3221 | 3221 | 3495 | 976 |
| Front Brake Pads (set of 4) | 12600 | 5960 | 5960 | 9952 | 9952 | 4811 | 4811 | 5186 | 5767 |
| **MECHANICAL PARTS** | | | | | | | | | |
| A/c Evaporator Coil | 11000 | 8279 | 8279 | 22859 | 22859 | 14618 | 14618 | 39303 | 20087 |
| Radiator Hose Set | 2000 | 2104 | 2104 | 540 | 540 | 865 | 865 | 1245 | 3503 |
| Front Strut/ Shock Absorber | 8543 | 11280 | 11280 | 6834 | 6834 | 4730 | 4730 | 9000 | 10727 |
| Front Brake Disc/ Drum | 6200 | 5845 | 5845 | 5237 | 5237 | 6077 | 6077 | 6007 | 4564 |
| Front Suspension Lower Arm | 17500 | 14011 | 14011 | 13722 | 13722 | 11398 | 11398 | 6500 | 8645 |
| Clutch and Pressure Plate | NA | 16050 | NA | 15639 | 15639 | 15075 | NA | 12200 | 19953 |
| Clutch Release Bearing | NA | 3916 | NA | 2900 | 2900 | 3997 | NA | 5703 | 3910 |
| **ACCIDENT REPAIR PARTS** | | | | | | | | | |
| Front bumper | 17500 | 15990 | 15990 | 11458 | 11458 | 14985 | 14985 | 12050 | 24532 |
| Wheel rim (each) | 22000 | 30500 | 30500 | 9334 | 9334 | 18178 | 18178 | 4834 | 17899 |
| Front fender | 13000 | 16216 | 16216 | 11425 | 11425 | 9628 | 9628 | 5352 | 13139 |
| Bonnet | 24000 | 20077 | 20077 | 34158 | 34158 | 19115 | 19115 | 16900 | 26743 |
| Radiator | 23000 | 14450 | 14450 | 16842 | 16842 | 10999 | 15210 | 15892 | 15714 |
| Front door | 35700 | 38305 | 38305 | 32217 | 33184 | 23318 | 23318 | 35000 | 24283 |
| Bootlid/ tailgate | 38000 | 25971 | 25971 | 32935 | 32935 | 33452 | 33452 | 25000 | 37436 |
| Headlight Assy. (each with bulb) | 25000 | 46999 | 46999 | 19721 | 19721 | 40237 | 40237 | 27223 | 37000 |
| Tail-light Assy. (each with bulb) | 7500 | 7045 | 7045 | 5450 | 5450 | 9439 | 9439 | 8200 | 12703 |
| Front windscreen glass | 17500 | 18455 | 18455 | 25089 | 25089 | 19850 | 19850 | 14648 | 18711 |
| Side mirror (with casing) | 19500 | 18549 | 18549 | 4825 | 4825 | 19328 | 19328 | 11152 | 4640 |
| **Total Price Basket** | 312493 | 333854 | 313888 | 294268 | 295235 | 290197 | 275336 | 278945 | 319918 |
| Vehicle price (ex showroom Mumbai, base version) | 2808056 | 2529468 | 2757457 | 2373485 | 2812346 | 3016031 | 3378121 | 2210341 | 2241877 |
| Percentage of parts to car price | 11.1% | 13.3% | 11.4% | 12.4% | 10.5% | 9.6% | 8.2% | 12.6% | 14.3% |




## VOLVO

| | S60 PETROL | S60 D4 DIESEL | S60 CROSS COUNTRY DIESEL | V40 DIESEL | V40 CROSS COUNTRY PETROL | XC60 D4 DIESEL | XC60 D5 DIESEL | XC90 DIESEL |
|---|---|---|---|---|---|---|---|---|
| **SERVICE PARTS** | | | | | | | | |
| Air Filter | 2563 | 2563 | 2563 | 2102 | 2102 | 2563 | 2563 | 2922 |
| Oil Filter | 1282 | 1282 | 1282 | 1282 | 923 | 1282 | 1282 | 1282 |
| Fuel Filter | 3434 | 3434 | 3434 | 3434 | 3434 | 3434 | 3434 | 3588 |
| Wiper Blades (pair) | 4727 | 4727 | 4727 | 4727 | 4727 | 4727 | 4727 | 4727 |
| Spark Plug (for entire set) | 7483 | NA | NA | NA | 7483 | NA | NA | NA |
| Timing Belt/ Chain | 13430 | 13430 | 13430 | 13430 | 13430 | 13430 | 13430 | 16914 |
| Fan Belt/ Drivebelt | 4561 | 3588 | 3588 | 3023 | 4561 | 3588 | 3588 | 4562 |
| Front Brake Pads (set of 4) | 9226 | 8201 | 9226 | 7893 | 7893 | 9226 | 9226 | 10148 |
| **MECHANICAL PARTS** | | | | | | | | |
| A/c Evaporator Coil | 51836 | 51836 | 51836 | 41948 | 41948 | 51836 | 51836 | 51835 |
| Radiator Hose Set | 5165 | 5165 | 5165 | 5165 | 5165 | 5165 | 5165 | 8050 |
| Front Strut/ Shock Absorber | 11687 | 11687 | 11687 | 10559 | 10559 | 10559 | 13633 | 18554 |
| Front Brake Disc/ Drum | 8919 | 8919 | 8919 | 7483 | 7483 | 10353 | 10353 | 11482 |
| Front Suspension Lower Arm | 15605 | 15605 | 17655 | 15605 | 15605 | 17655 | 17655 | 67090 |
| Clutch and Pressure Plate | NA | NA | NA | NA | NA | NA | NA | NA |
| Clutch Release Bearing | NA | NA | NA | NA | NA | NA | NA | NA |
| **ACCIDENT REPAIR PARTS** | | | | | | | | |
| Front bumper | 63700 | 63700 | 63700 | 59887 | 59886 | 71186 | 71186 | 78248 |
| Wheel rim (each) | 58365 | 58365 | 58365 | 45380 | 30754 | 45380 | 45380 | 92947 |
| Front fender | 32627 | 32627 | 32627 | 29661 | 29661 | 36440 | 36440 | 54943 |
| Bonnet | 71045 | 71045 | 71045 | 63277 | 63277 | 84887 | 84887 | 103248 |
| Radiator | 32121 | 32121 | 32121 | 27234 | 27234 | 32121 | 32121 | 44537 |
| Front door | 67796 | 67796 | 67796 | 64548 | 27234 | 79519 | 79519 | 103671 |
| Bootlid/ tailgate | 58050 | 58050 | 58050 | 54095 | 54095 | 84604 | 84604 | 102401 |
| Headlight Assy. (each with bulb) | 78595 | 78595 | 78595 | 58710 | 58661 | 53080 | 53080 | 143521 |
| Tail-light Assy. (each with bulb) | 19591 | 19591 | 19591 | 19592 | 19592 | 22211 | 22211 | 22667 |
| Front windscreen glass | 58023 | 58023 | 58023 | 58023 | 36495 | 52589 | 52589 | 70941 |
| Side mirror (with casing) | 26412 | 26412 | 26412 | 24152 | 24152 | 24152 | 24152 | 42640 |
| **Total Price Basket** | 706243 | 696762 | 699837 | 621210 | 556354 | 719987 | 723061 | 1060918 |
| Vehicle price (ex showroom Mumbai, base version) | 4613325 | 3875876 | 4470696 | 3099007 | 3694507 | 5237654 | 5581984 | 7759440 |
| Percentage of parts to car price | 15.3% | 18.0% | 15.7% | 20.0% | 15.1% | 13.7% | 13.0% | 13.7% |




PERSONAL ACCIDENT (GROUP) COMMERCIAL

• Restricted Cover - Death only
• Death, Permanent Disablement and Temporary Total Disablement.
For more details on risk factors, terms & conditions please read sales brochure carefully before concluding a sale.
*Condition apply
NEW INDIA ASSURANCE
दि न्यू इन्डिया एश्योरन्स कंपनी लिमिटेड
The New India Assurance Co. Ltd
www.newindia.co.in
Toll free 1800-209-1415
Regd & Head Office: New India Assurance Bldg., 87, M.G. Road, Fort, Mumbai-400 001, INDIA
IRDAI REGN. No. 190 CIN : U 99999 MH 1919 GOI 000 526 UIN. IRDAN190P0003V01201314 URN No. : NIA/16-17/PC/292

PERSONAL ACCIDENT- INDIVIDUAL RETAIL

• Restricted Cover - Death only
• Death, Permanent Disablement and Temporary Total Disablement.
For more details on risk factors, terms & conditions please read sales brochure carefully before concluding a sale.
*Condition apply
NEW INDIA ASSURANCE
दि न्यू इन्डिया एश्योरन्स कंपनी लिमिटेड
The New India Assurance Co. Ltd
www.newindia.co.in
Toll free 1800-209-1415
Regd & Head Office: New India Assurance Bldg., 87, M.G. Road, Fort, Mumbai-400 001, INDIA
IRDAI REGN. No. 190 CIN : U 99999 MH 1919 GOI 000 526 UIN. IRDAN190P0002V01201314 URN No. : NIA/16-17/PC/292